



**RECREATIONAL VEHICLE SERVICE CAMPAIGN**

July 30, 2014

Service Advisory: 14-211

**CSC-10056397-9103**

**SERVICE CAMPAIGN**

«Name»

«Address»

«City», «State» «Zip»

«Country»

VIN: «VIN»

Dear «Name»:

Keystone RV Company is conducting a service campaign on certain 2014-2015 Bullet 310BHS Travel Trailers. We apologize for any inconvenience this action may cause you; however your continued satisfaction is of the utmost importance to us.

***Reason for this campaign***

It has been determined that certain Bullet model 310BHS are missing a door stop on the exterior shower located above the water heater. The missing stop will allow the shower door, when in the open position, to contact the water heater exhaust grill leading to the potential for heat damage to the exterior shower door when the water heater is in operation.

***What we will do***

Keystone has notified our dealers regarding this situation. The remedy is to install the missing door-stop to maintain proper opening angle. The service required for this corrective action will be provided at no charge to you.

***What we need you to do***

At your earliest convenience, please make an appointment to have your RV serviced by your dealership. The labor time to perform this campaign is approximately ½ hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

Thank you for your attention and cooperation in this matter.

Sincerely,

**KEYSTONE RV COMPANY**

Rick Deisler  
Sales & Service Manager