

Subject NY Taxi vinyl cover installation CAUTION		Market USA
Service Category Vehicle Interior	Section Meter/Gauge/Display	
Applicability Prius V, Camry HV		

APPLICABLE VEHICLES






2012-2015	Prius V	2011-2015	Camry HV
-----------	---------	-----------	----------

CONDITION

In some areas such as New York, taxi companies are required to install vinyl covers on or around the rear seat. When installing the vinyl cover near the rear seat, the HV Battery cooling system air inlet screen could be covered by mistake. **Do not block the HV battery cooling system air inlet screen.**

RECOMMENDATIONS

Based on the vehicle you are working on, (For example New York taxis) the table below indicates certain cutout areas on the required vinyl cover. These cutouts are needed to allow proper air flow to the HV Battery cooling system.

	No Good	OK
<p>Prius V</p> <p><TSB> Cooling fan maintenance T-SB-0162-13 Cooling fan Intake filter T-SB-0171-13</p>	 <p>Cooling fan inlet is covered by vinyl floor.</p>  <p>Cooling fan inlet is clogged or covered by dust, debris or additional seat cover.</p>	 <p>Secure cooling fan inlet area by cutting off, cleaning or securely installing.</p>
<p>Camry HV</p> <p><TSB> Cooling fan maintenance T-SB-0087-13 Cooling fan Intake filter T-SB-0088-13</p>	 <p>Cooling fan inlet is partially covered by additional seat cover.</p>	 <p>Secure cooling fan inlet area by cutting off, cleaning or securely installing.</p>

Caution: Failure to cut out vinyl cover at HV Battery cooling system air inlet screen area will result in premature HV Battery damage

LINK REFERENCES

This Tech Tip does not contain any link references