

VIN:
UNIT:

SERVICE BULLETIN FUEL FILL HOSE SEAT PLATE INTERFERENCE

Models affected: Collins Bus Models with seats installed over the fuel tank fill hose.

This Service bulletin is intended to assist Collins Bus Distributors, their customers and /or service shops in the proper technique for repair and maintenance of the issue described within this bulletin. Collins Bus Corporation has determined that on certain Collins Bus seating configurations the seat mount plate may have a sharp cut edge. If this edge comes in contact with the fuel fill hose a possible weakening of the hose wall may occur over time. While no damage has been reported we feel this possibility may exist and your bus should be inspected for this possible condition.



Fuel Fill Hose under bus behind driver's side skirt




Seat mount plate sharp edge could rub on the fuel fill

If during inspection of the fuel fill hose to the mid-ship fuel tank you find the cut edge of the seat mount plate is directly above the fuel fill hose and making contact, a seat mount plate cover (442290) should be installed.
Remove the seat bolt nut closest to the fuel fill hose.



Slide the plate cover (442290) over the seat mount plate until the holes are aligned. This cover will keep the sharp cut edge on the seat mount plate from making contact with the fuel fill hose.

Seat mount plate cover



Seat mount plate

Replace the seat bolt nut and tighten to 12-14 ft. lbs.

