

GM CUSTOMER CARE AND AFTERSALES
DCS3469
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 4, 2014

Subject: 14154 – Service Update Bulletin
220 Amp Generator Fuse Block Corrosion
VIN List Attached

Models: 2015 Chevrolet Silverado 2500 HD
2015 GMC Sierra 2500 HD
Equipped with 220amp Generator (RPO KW5)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

Global Connect message G_0000205220 dated November 21, 2014, announced the release of Service Update Bulletin 14154. The message did not include a BAC sorted VIN list identifying involved in-stock units. This has been corrected, please see the attached VIN list along with a courtesy copy of the bulletin. We apologize for any inconvenience this may have caused.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES