

DART: Bulb Seal Addition to CNG Line Cover



Prepared by: John Gunter
Field Service Rep.

Approved by: Dan Allen
Chief Engineer of Manufacturing and Service Support

Property name and Top bus number: DART -304500-306500-313000-314000

Issue: CNG line cover contacting the roof of the bus

Reason/ cause: Cover needs an isolator

Solution: Add bulb seal per this work instruction.



DART: Bulb Seal Addition to CNG Line Cover



1. Park the bus and apply the parking brake.
2. Turn off main battery disconnect switch.
3. On the C/S roof where the CNG cover makes a "Y", add 2' of bulb seal as shown in the picture below.



Add 2' of bulb seal as shown.

4. Check for completeness of work.
5. Remove all tools from work area.
6. Turn the main battery disconnect switch on.