



PARTS  
ALERT

Possible 'Missing' Water Pump Bolts [C2Z21781,  
C2Z28248, C2Z29189]

11-JUL-14

No.: JA14PA-11

Section: GENERAL  
INFORMATION

Market: CAN / USA

Please be advised that Water Pump part numbers C2Z21781, C2Z28248, and C2Z29189 -- 3.0L V6 / 5.0L V8 -- come with four (4) mounting bolts.

Prior to installing this part, inspect the packaging and make sure all four (4) bolts are present.

**If one or more of the mounting bolts is missing, do not install the pump without first locating all four (4) bolts.**

The 'missing' bolt(s) may be inside the pump. Using this water pump may result in engine failure.

If the mounting bolt cannot be easily extracted, please return the part via a Faulty (FLT) DY.