

Attachment 1.jpg

Attachment 2.jpg

Reference	SSM71793
Models	Range Rover Evoque / L538
Title	Evoque Wheelarch Cladding Clips and Hooks
Category	Body
Last modified	11-Apr-2014 00:00:00
Symptom	108000 Ext. Trim/Accessories
Content	<p>Issue: Jaguar Land Rover are seeking information concerning Wheel arch cladding clips and hooks</p> <p>Cause: The root cause is being investigated and information is required</p> <p>Action: Where any repairs on Wheel arch cladding clips and hooks are undertaken please raise an EPQR with answers to the following questions</p> <ol style="list-style-type: none">1) Is the issue with the Front or Rear cladding?2) In which area is the part loose?3) Are any of the clips loose or broken?4) If yes please identify which clip using the numbers in attachment 15) If the issue is with the Front cladding is the Hook engaged? See attachment 26) Is the Hook marked or deformed?



3

4

5

6

7

8

