

Reference	SSM71845
Models	Range Rover / L405 Range Rover Sport / L494
Title	Brake Squeal from 350mm (19 Inch) Rear Brakes
Category	Chassis
Last modified	14-May-2014 00:00:00
Symptom	301000 Service Brake System
Attachments	350mm 19 Inch Rear Brake Pad Greasing.pdf
Content	<p>Issue:</p> <p>Customers reporting a squeal noise during braking that is coming from the rear of the vehicle. (Vehicles fitted with 350mm diameter rear discs as found on 3.0 liter L405/L494 vehicles).</p> <p>Cause:</p> <p>Land Rover Engineering are aware of the issue and currently investigating what permanent fix can be implemented to resolve the concern.</p> <p>Action:</p> <p>Please apply "Never-seezbrandregular grade grease" (widely available from auto parts retailers)to the brake pad abutments and the outboard brake pad back plate. Do not apply to the inboard pad back plate, only the abutments. Please refer to attachment for further guidance on where to apply grease.</p>