

Reference	SSM71901
Models	LR4 / L319 Range Rover Sport / L320
Title	Dash Topper Pad Creak 10 MY Onwards
Category	Body
Last modified	03-Jul-2014 00:00:00
Symptom	107000 Interior Trim
Content	<p><u>Issue:</u> Customer complaint of noise from facia when travelling over certain road conditions.</p> <p><u>Cause:</u> JLR engineering have found during their investigations that the instrument panel upper section speaker aperture bolt may have a relaxed torque (See TOPIx workshop manual section 76.46.04 Fig. E12471)</p> <p><u>Action:</u> Release the instrument panel upper section speaker aperture bolt and over torque back to 13Nm</p>