

<b>Reference</b>	SSM71959
<b>Models</b>	LR4 / L319 LR3 / L319 Range Rover / L405 Range Rover Sport / L494 Defender / L316 Range Rover Evoque / L538
<b>Title</b>	Bonnet or Tailgate Land / Range Rover Badge Discolouration
<b>Category</b>	Body
<b>Last modified</b>	26-Aug-2014 00:00:00
<b>Symptom</b>	108000 Ext. Trim/Accessories

**Content****Issue:**

Discoloration or peeling of the front or rear Land Rover or Range Rover badge

**Cause:**

Supplier quality issue with the coating on the badge , this has now been resolved and assured Vins are below

L494 - LW384250

L405 - LG181175

L319 - LA726850

L316 - LD456088

L538 - LV966157

**Action:**

Replacement is the only repair option for this issue. Service parts have been purged and replaced with parts at the revised level.

**JLR Engineering would like to thank everyone who submitted reports highlighting this issue, please only submit further reports for vehicles that are post the assured VIN's above or repeat repairs that have had new parts fitted post 18/8/2014**