



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** PQC Part Restriction On Gear Kit For 2013-2014 Chevrolet Camaro Equipped With RPO (1LE) Only

**Models:** 2013-2014 Chevrolet Camaro with RPO 1LE

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The 3.91 gear Kit for the 1LE equipped vehicles has been placed on a PQC parts restriction

### Recommendation/Instructions

Please contact PQC with the vehicle identification Number, if you require P/N 22813040 (3.91 gear Kit) for the 2013-2014 Chevrolet Camaro equipped with RPO 1LE

If you are attempting to order this gear set for 2010-2014 (NOT equipped with RPO 1LE) please use P/N 22959394 or refer to the latest Chevrolet Performance Parts Catalog for NON RPO (1LE) applications.

Please contact PCC at (866)453-4123, If you have additional questions concerning the 3.91 gear set

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION