



Service Bulletin

PRELIMINARY INFORMATION

Subject: 2014 Impala And Malibu 2.5L LKW Engine Exchange And PQC Restriction Has Ended

Models: 2014 Chevrolet Impala
2014 Chevrolet Malibu
Equipped with the 2.5 (LKW) engine
P/N 12656342 NU6 Calif / NE emissions
P/N 12656343 NU5, NT7 Federal emissions

This PI was superseded to end the part restriction. Please discard PIP5106D.

The 2014 Impala and Malibu 2.5L LKW Engine Exchange and PQC Restriction has ended.

It is no longer necessary to contact PQC for the 2.5 (LKW) engine P/N 12656342 RPO (NU6) Calif / NE emission and P/N 12656343 RPO (NU5, NT7).

Dealers can now order these parts through their dealership parts department process.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION