



Service Bulletin

PRELIMINARY INFORMATION

Subject: TAC Part Restriction Ended - Accessory DC Power Control Module (APM)

Models: 2011-2015 Chevrolet Volt
2014-2015 Cadillac ELR

This PI was superseded to end Part Restriction. Please discard PIP4844C

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The Part Restriction for the Accessory DC Power Control Module (also known as the APM or 14V Power Module) part number 22753244 & 24262768 has ended. Thank you for your assistance in collecting data.

Recommendation/Instructions

These part number can now be ordered directly through your parts department without TAC authorization.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION