



# Service Bulletin

File in Section: -

Bulletin No.: PI1023B

Date: November, 2014

## PRELIMINARY INFORMATION

**Subject:** Elimination of Rear Seat Floor Filler Trim Panel as Standard Equipment

**Models:** 2014-2015 Chevrolet Equinox  
2014-2015 GMC Terrain

This PI has been revised to add the 2015 model year. Please discard PI1023A.

### Condition/Concern

Some customers may comment that their vehicle is missing the rear seat floor filler trim panel.



3559594

As shown is the graphic above, in previous models years 2010-2013, these vehicles included the rear seat floor filler trim panel as standard equipment.



3559595

Starting with 2014 vehicle production, the floor filler trim panel was eliminated as standard equipment. The seat/floor interface will now look like the example shown in the graphic above.

### **Recommendation/Instructions**

No repairs are necessary and please advise the vehicle owner of the standard equipment change.

**Note:** The installation and cost of adding the floor filler panel will not be covered under the vehicle's warranty and would be at the customer's expense.