

**Countries:** CANADA, UNITED STATES**Availability:** ISIS**Major System:** ENGINES**Current Language:** English**Other Languages:** NONE**Viewed:** 90**Document ID:** IK1201101**Revision:** 0**Created:** 3/13/2014**Last Modified:** 3/17/2014**Author:** Steven Bell[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 3	 1

Title: 2007-2009 EPA MaxxForce 11/13L Camshaft Cap Bolt Torques**Applies To:** 2007-2009 EPA MaxxForce 11/13L

CHANGE LOG

DESCRIPTION

The torque spec for the camshaft cap bolts changed early in the production of the 2007 Maxxforce IBB engine. The change is not reflected in the manual correctly. The torque spec is dependent on if the 7th digit of the engine serial number is a D or Y.

Example A) 124HM2Y4012084- The torque spec is 18ft. lbs.

Example B) 124HM2D4012084- The torque spec is 26ft. lbs.

The 2010 and 2013 MaxxForce IBB manuals are correct and should be followed for their respective engines.

Hide Details

Feedback Information

Viewed: 89

Helpful: 3

Not Helpful: 1

Staff ID	Client ID	Comments	Created Date
	DY08955	You received the following feedback From: dy08955 - David Gabrielle Email Address: gabe396@aol.com Job Classification: SE008, Service Technician Dealer: TRUCK KING INTL IDEALEAS Feedback: You state: The change is not reflected in the manual correctly. Please correct the Engine Service Manual information.	3/20/2014 5:32:00 AM

--

Copyright © 2014 Navistar, Inc.