



Countries:	CANADA, UNITED STATES	Document ID:	IK1500076
Availability:	ISIS	Revision:	0
Major System:	FUEL SYSTEMS	Created:	3/7/2014
Current Language:	English	Last Modified:	3/17/2014
Other Languages:	NONE	Author:	Tyler Oberhelman
Viewed:	193		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 2	 2

Title: SPN 94 FMI 0 Fuel Delivery Pressure Above Maximum

Applies To: EPA 2010 Maxxforce 11/13 ProStar, WorkStar, TransStar, LoneStar, PayStar

CHANGE LOG

If this iKNOW Article is being revised, please type in the text box what has changed in the article. The change log is meant for Dealers to be able to see what has updated/changed in the article.

Added note in fuel filter section of ****Only use non-alcoholic anti-gel****

SPN 94 FMI 0 – Fuel Delivery Pressure Above Maximum

Fault Overview

Fault code sets when signal from the Fuel Delivery Pressure (FDP) sensor indicates FDP exceeds 130psi at low idle and 145psi above idle

Possible Causes

- Restricted secondary fuel filter caused by gelling, icing, or debris

FUEL FILTER

Service Interval: 40,000 km (25,000 miles), 12 months, 1,100 hours or 16,000 liters (4,200 gallons) of fuel

Steps:

If code becomes active and secondary filter has not been replaced recently, inspect for restricted filter or gelling. (Replace filter or add anti-gel in winter conditions)

****Only use non-alcoholic anti-gel****

If fault remains active deliver to dealer for diagnostics and repair.

International® trucks are designed and built to operate satisfactorily on fuels and lubricants of good quality marketed by the petroleum industry. Use of any supplementary fuel or lubricant additives is not recommended. Malfunctions attributed to the use of such additives or failure to follow recommended fuel or lubricant recommendations may not be covered by any applicable warranty.

****Note-Filter replacement is maintenance item and not covered under warranty****

 Hide Details

Feedback Information

Viewed: 192

Helpful: 2

Not Helpful: 2

No Feedback Found

Copyright © 2014 Navistar, Inc.