

46 Brake noise analysis and handling

46 14 67 2034181/5 January 21, 2014. Supersedes Technical Service Bulletin Group 46 number 14-64 dated January 2, 2014 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
R8	2014	All	Without ceramic brakes	
A6	2013	051000 - 999999	2.0T	
A6	2014	All	2.0T	
A6	2012-2014	All	3.0T & 4.0T	
A7	2012-2014	All	Not Applicable	
A5/S5	2013	902741 – 999999	Not Applicable	
A5/S5	2014	All	Not Applicable	
A5/S5 Cabrio	2013	900474 – 999999	Not Applicable	
A5/S5 Cabrio	2014	All	Not Applicable	
A4/S4	2013	A125000 – A999999 N020500 – N999999	Not Applicable	
A4/S4	2014	All	Not Applicable	
Allroad	2013	125000 – 999999	2.0T	
Allroad	2014	All	2.0T	
Q5 hybrid	2013	010908 - 999999	Hybrid	
Q5 hybrid	2014	All	Hybrid	
RS 5	2013	902741 - 999999	Without ceramic brakes	
RS 5	2014	All	Without ceramic brakes	
RS 5 Cabrio	2013	900474 - 999999	Without ceramic brakes	
RS 5 Cabrio	2014	All	Without ceramic brakes	
TT/TTS	2013 -2014	All	Not Applicable	

© 2014 Audi of America, Inc.

Page 1 of 6

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Condition

REVISION HISTORY				
Revision	Date	Purpose		
5	-	Revised header data (Restructured model codes)		
4	01/02/2014	Revised header data (Added model years)		
3	12/5/2013	Revised Warranty (Changed codes)		
2	8/16/2013	Revised header data (Corrected applicable model code)		
1	08/07/2013	Initial publication		

Customer may report hearing brake noise from front or rear brakes. Customers may describe these noises as a squeal, squeak, grinding, groaning, thumping, or creaking.

Technical Background

Note: Before proceeding with any of the following steps, check for any applicable TSBs for brake noise. Also refer to the Audi Brake Systems brochure for helpful information.

Brake noise can be attributed to many causes. Seven of the most common causes are:

- 1. Brake discs or brake pads are close to or below their wear limit.
- 2. Aftermarket pads or discs have been installed.
- 3. There is debris (such as small stones, grit, road salt, or sand) between brake disc and brake pad.
- 4. Discs are covered with rust. Rust can form when the vehicle has not been driven for a long period of time (Figure 1).



Figure 1. Disc covered with rust.

Page 2 of 6

^{© 2014} Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



5. Discs are grooved (Figure 2).



Figure 2. Grooved disc.

6. There is chemical contamination on the braking surface of the brake disc due to wheel or tire cleaner being sprayed directly onto the brake disc (Figure 3 and Figure 4).



Figure 3. Discoloration on the brake disc due to chemical contamination from cleaner that was sprayed directly onto the disc.

© 2014 Audi of America, Inc.

Page 3 of 6

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.





Figure 4. Small spots and discoloration due to chemical contamination from cleaner that was sprayed directly onto the disc.



Figure 5. Brake pad material has transferred to the discs.

Production Solution

snowy environment.

of brake pad material transferring to the discs (Figure 5). Pad marks can occur when a vehicle

Not applicable.

© 2014 Audi of America, Inc.

Page 4 of 6

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Service

For vehicles within the New Vehicle Limited Warranty, Audi of America is requesting your cooperation in supplying us with technical information regarding brake noise.

- 1. Check the overall condition of the brakes to determine if the brake noise is caused by one of the causes listed in the *Technical Background* section of this bulletin. If the noise is not a result of one of these causes, proceed with the following steps.
- 2. Determine the location of the brake noise (e.g., left front, front axle, rear axle, etc.):
 - Knowing the location of the noise on the vehicle is critical to properly addressing the concern.
 - It may be necessary to have an assistant listening from inside or outside of the vehicle to accurately determine the location.
- 3. Obtain a sound or video recording and fill out questionnaire:
 - The sound recording can be from a cell phone as long as the noise can be clearly identified.
 - Recordings submitted by customers are also acceptable.
 - In order to minimize file size, only sound recordings are necessary. Videos should only be sent if it is critical for understanding the conditions under which the noise occurs.
 - Fill out as much information as possible in the questionnaire. Some fields are mandatory.
- 4. Clean the brake pads and discs:
 - 1. With careful consideration of the traffic situation, perform between 2 and 5 ABS stops from speeds above 50 mph. Between each ABS stop, allow the brake components to cool by driving the vehicle for more than one minute at speeds greater than 50 mph.
 - 2. Let vehicle sit for two hours to cool down.
 - 3. Test drive again. If the noise was not eliminated after completion of steps 1 and 2 please contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.
- 5. Provide feedback to Audi of America:
 - 1. Fill out the attached questionnaire with as much detail as possible.
 - 2. Email the questionnaire and sound or video recording to: chassis@audi.com.
 - 3. The subject line of the email should contain the VIN of the vehicle you are working on.
 - 4. Include the following information in the body email:
 - Mileage
 - TAC access code (if applicable)
 - Repair order number

© 2014 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	Front - 4617				
Damage Code:	0020				
Diagnostic Time:	Clean brake pads and discs Includes: Road tests, submission of audio file and questionnaire	4617 8099	70 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2034181/5				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2034181) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2014 Audi of America, Inc.

Page 6 of 6

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.