

1 10 03-14



## Service Information Bulletin

SUBJECT	DATE
Rough Running or Stalling	October 2014

### Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0009	EPA07 Series 60	Improper Injector Calibration Setting	New graphic.




13400 Outer Drive, West, Detroit, Michigan 48239-4001  
 Telephone: 313-592-5000  
[www.demanddetroit.com](http://www.demanddetroit.com)

## 14.5 IMPROPER INJECTOR CALIBRATION SETTING

To determine if improper injector calibration setting is causing rough running or stalling, perform the following steps:

1. Test for improper injector setting.
2. Compare the calibration code(s) shown on the DiagnosticLink® display with the calibration code(s) on the injector(s). See Figure 14-1.



47960

**Figure 14-1**      **Injector Calibration Code**

- [a] If the calibration codes match, check compression pressure; refer to section 14.6.
- [b] If the calibration code on the display is different than the calibration code on the suspect injector for that cylinder, the injector setting must be reset, see Figure 14-1; refer to section 14.5.1.

### 14.5.1 Improper Injector Setting Repair

Perform the following steps to recalibrate improper injector setting:

1. Reset incorrect injector setting.
2. Verify injector setting repair.

## **ADDITIONAL SERVICE INFORMATION**

Additional service information is available in *Power Service Literature*.



13400 Outer Drive, West, Detroit, Michigan 48239-4001  
Telephone: 313-592-5000  
[www.demanddetroit.com](http://www.demanddetroit.com)