

[Next Unread Message](#)**View Message****Sent on** 07 30 2014 **Expires on** 08 13 2014**From** Parts and Service Division**Subject** Request for Visit: 2014-2015 Pilot Soft Brakes (Zone 6)

**To:** All Honda Service Managers/Advisors  
**From:** Technical Research & Support Group  
**RE:** Request for Visit: 2014-2015 Pilot Soft Brakes (Zone 6)

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda (AHM) is investigating certain 2014-2015 Pilots with a complaint of brakes having a soft feel or having excessive pedal travel. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to your attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. No previous repair on the brakes.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.