

[Next Unread Message](#)**View Message**

Sent on 07 24 2014 **Expires on** 08 07 2014
From Parts and Service Division
Subject Request for Info: 2014 MDX Steering Wheel Vibration

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Info: 2014 MDX Steering Wheel Vibration

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2014 MDXs with a complaint of steering wheel vibration due to wheel/tire imbalance. To fully understand the cause of this condition, AHM would like to collect pertinent information from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must be able to duplicate the issue.
2. Mileage must be less than 10,000 miles.
3. No previous wheel balance repair.
4. All 4 tires must be original OEM tires.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.