

[Next Unread Message](#)**View Message**

Sent on 03 18 2014 **Expires on** 04 01 2014
From American Honda Parts, Service & Technical Division, Campaign Administration
Subject Stop Sale/Safety Recall: 2005-10 Odyssey Fuel Pump Module Leak

DATE: March 13, 2014

TO: All Honda Sales, Service & Parts Managers and Personnel
FROM: American Honda Parts, Service & Technical Division, Campaign Administration

RE: Stop Sale/Safety Recall: 2005-10 Odyssey Fuel Pump Module Leak

On March 13, 2014 American Honda will notify NHTSA of a **Stop Sale** order and **Safety Recall** for all 2005-10 Odyssey vehicles. Any used vehicles in dealer stock must be inspected, and if necessary, repaired per S/B 14-015, *Safety Recall: Odyssey Fuel Leak or Smell* prior to sale. **Refer to the eResponsibility report or VIN Inquiry status to determine which vehicles in your inventory are affected.**

Affected vehicles should not be sold until the inspection, and if necessary, repair has been completed. Should an unrepaired vehicle cause any injury or damage because of the required recall repair, the dealership will be solely responsible to the damaged party, and will be required to defend and indemnify Honda for any resulting claims.

This campaign will have two phases. During the first phase, customers will be notified of the recall. If a customer comes in and either complains of a fuel smell, fuel leak or requests an inspection, refer to the inspection and repair procedure in this bulletin. Otherwise, customers should wait until the second phase of the recall. For the second phase, all vehicles identified in the VIN status inquiry will receive improved parts, including those that previously had the fuel filter set replaced with original parts.

Basic Problem

Over time, the fuel filter assembly may be exposed to certain conditions, which may cause the filter set cover to crack and allow customers to notice a fuel smell.

The Repair

Affected vehicles require inspection of the fuel filter set. Any vehicles exhibiting leaks as outlined in service bulletin 14-015 will require application of a pre-countermeasure fuel filter set. In Summer 2014, countermeasure parts will become available; at that time, the inspection procedure will be removed and countermeasure parts application will begin for **all** affected vehicles.

Parts Information

Parts to permanently repair affected vehicles will be available in Summer 2014. Until that time, pre-countermeasure fuel filter sets will be used to temporarily repair vehicles. Pre-countermeasure fuel filter sets will not be available for open order; instead, please advise your DPSM of all pre-countermeasure parts needs. Your DPSM will facilitate getting an order in the system (note: this is the same process employed for the Odyssey VSA software error safety recall), and a part allocation will be made.

Special Tools Information

Service Bulletin 14-015 includes a reference to commercially available Developer. The correct material to use in this case is D70 Developer, P/N MCED70, which is available through the Tool and Equipment Program by calling 888-424-6857. The material is not available for order through the iN.

Service Bulletin

In support of this recall, S/B 14-015 will be posted on ISIS on March 13, 2014. It will include inspection, temporary repair, parts, and warranty information related to this campaign.

Warranty and Repair Information

Warranty, inspection and temporary repair information will be detailed in S/B 14-015, *Safety Recall: Odyssey Fuel Leak*

or Smell.

Customer Notification

Honda expects to complete initial customer notification by the middle of May 2014. Secondary notifications announcing availability of the countermeasure parts will begin to be issued some time in Summer 2014.

As always, make sure to check in VIN Inquiry status to determine if a vehicle is eligible for this recall.

Click [here](#) for a copy of service bulletin 14-015.

Click [here](#) for the Q&A File in PDF format.

[▲ BACK TO TOP](#)

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.