

[Next Unread Message](#)**View Message**

**Sent on** 02 27 2014 **Expires on** 03 12 2014  
**From** Parts and Service Division  
**Subject** Request for Parts: 2010 & 2013 MDX & TSX Steering Wheel Vibration When Braking

**To:** All Acura Service Managers/Consultants  
**From:** Technical Research & Support Group  
**RE:** Request for Parts: 2010 & 2013 MDX & TSX Steering Wheel Vibration When Braking

This message is solely directed to Acura dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

**Background**

American Honda (AHM) is investigating certain 2010 & 2013 MDXs & TSXs with a complaint of the steering wheel vibration and the pulsation/vibration in the front brake when braking. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must be able to duplicate the vibration in the steering wheel and the pulsation/vibration in the front brake.
2. Note the vehicle speed when this issue occurs.
3. Mileage must be less than 60,000 miles.
4. If the vehicle has already had a repair on the front brakes, the last repair history must be provided.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.