



Countries: CANADA, UNITED STATES, PUERTO RICO **Document ID:** IK0800326
Availability: ISIS, FleetSIS **Revision:** 4
Major System: ELECTRICAL SYSTEM **Created:** 1/5/2012
Current Language: English **Last Modified:** 2/12/2014
Other Languages: NONE **Author:** Jon Pierce
Viewed: 2967

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 197	Not Helpful 80
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	---------------------------	------------------------------

Title: ProStar with feature code 0008TSJ Auto Start Stop Troubleshooting

Applies To: ProStar

DESCRIPTION

Feature code 0008TSJ for auto start stop is a feature that will allow you to preset values in the body controller to allow the truck to start when the battery voltage or engine oil temperature reaches the preset value. For operators manual for auto start stop [CLICK HERE](#).

TROUBLESHOOTING

- For troubleshooting guide for auto start stop [CLICK HERE](#)
- Below are the updated Body Controller Auto Start Stop Default Settings, these settings provide optimal performance.

Y ID	Parameter	Value	Unit	Description	Cfg. Value	Cfg. Unit
2778	Auto_SS_AC_Pwr_Fuse		10A	Auto start stop no idle AC...	100	A/10
2774	Auto_SS_Acc_Pwr_Fuse		10A	Auto start stop accessory ...	100	A/10
2779	Auto_SS_Heat_Pwr_Fuse		10A	Auto start stop no idle he...	100	A/10
2775	Auto_SS_Ign_Pwr_Fuse		10A	Auto start stop ignition R...	100	A/10
2776	Auto_SS_Iso_Pwr_Fuse		10A	Auto start stop battery is...	100	A/10
2777	Auto_SS_Starter_Pwr_Fuse		10A	Auto start stop starter RP...	100	A/10
3032	Auto_SS_Ambient_Temp_CAP		56.019F	The ambient temperature ab...	9163	K/32
2829	Auto_SS_Start_Temperature		50F	This parameter provides th...	10	C
2830	Auto_SS_Stop_Temperature		100.4F	This parameter provides th...	38	C
2674	Auto_SS_Horn_Enable	<input checked="" type="checkbox"/>	On/Off	Parameter to disable/enabl...	1	On/Off
2825	Eng_Oil_Temp_Enable	<input checked="" type="checkbox"/>	On/Off	Parameter enables/disables...	1	On/Off
2530	Wait_To_Start_Bypass	<input checked="" type="checkbox"/>	On/Off	Enables the wait to start ...	1	On/Off
3031	Auto_SS_Engine_CAP_Speed		1000RPM	The engine speed below whi...	8000	RPM/8
2743	Battery_High_Trip_Point		12.7V	Trip point to indicate whe...	254	V/20
2536	Battery_Low_Trip_Point		12.1V	Trip point to indicate whe...	242	V/20
2863	Auto_Start_Shutdown_Time		20min	Amount of time after the i...	20	min
2537	Battery_Run_Time		70min	Time that the engine will ...	70	min
2742	Engine_Run_Time		5min	This parameter specifies t...	5	min
2862	High_Temperature_Time		1min	Amount of time the engine ...	1	min
2861	Low_Temperature_Time		15min	Amount of time the engine ...	15	min
2837	Cruise_Control_Enable_Param		1000ms	time used in engine ramp f...	100	timercounts
2838	Cruise_Control_Resume_Param		1500ms	timing for engine ramp for...	150	timercounts
2836	Cruise_Control_Set_Param		500ms	time used in engine ramp c...	50	timercounts
3030	Auto_SS_Engine_CAP_Delay		120s	The amount of delay time t...	12000	timercounts
2538	Engine_Idle_Delay		90s	Amount of time before the ...	9000	timercounts
2541	Engine_Ramp_Delay		5s	Amount of delay time that ...	500	timercounts
2839	Key_Chk_Time		30s	Specifies the maximum amou...	3000	timercounts
2571	Low_Battery_Time		30s	This defines the amount of...	3000	timercounts


Applies to International engine only, for ISX, leave checkbox Checked For IBB, leave unchecked

- For the correct engine parameter use ServiceMaxx and apply this [TEMPLATE](#)
- For circuit diagram for auto start stop [CLICK HERE](#)
- For troubleshooting use this [SESSION](#) in DLB. Save session to desktop then follow procedure to load the session in DLB

- How to load session in DLB [Click Here](#)

NOTE:

**The Description starts in Section 7, page 27.
The Troubleshooting starts in Section 8, page 38.**

 Hide Details	Feedback Information
	Viewed: 2966 Helpful: 197 Not Helpful: 80
No Feedback Found	

Copyright © 2014 Navistar, Inc.