



Countries: AUSTRALIA, BRAZIL, CANADA, COLOMBIA, UNITED STATES, PUERTO RICO, SOUTH AFRICA

Document ID: IK1300036

Availability: ISIS

Revision: 3

Major System: TRANSMISSION

Created: 9/17/2007

Current Language: English

Last Modified: 4/28/2014

Other Languages: [Français](#), [Español](#),

Author: Matthew Boyer

Viewed: 830

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 161	 260

Title: Freedomline Transmission 1939 Datalink Overlay

Applies To: Model: 9200i End Date: 12/05/2005 9400i End Date: 12/05/2005 9900i End Date: 12/05/2005

DESCRIPTION

This article applies to 9000i models built prior to December 5, 2005 with Cummins ISX engine and Freedomline transmission.

The original J1939 Data Link Backbone runs through several connectors between the engine ECM, transmission ECU, and ABS ECU and can cause excessive resistance and intermittent loss of communication between the respective controllers. This loss of communication can result in various Diagnostic Trouble Codes (DTC's). The new Service Parts Kit contains harnesses and the installation instructions to eliminate the connectors between the controllers used with the Freedomline transmission and the Cummins ISX engines.

PARTS INFORMATION

2595189C91, Kit, Harness, Freedomline

Service Procedure

Obtain the International Service Parts Kit listed in the Parts Information section of this letter and install as directed in the Installation Instructions that are provided in the kit.

Hide Details

Feedback Information

Viewed: 829
Helpful: 161

Not Helpful: 260

No Feedback Found

Copyright © 2014 Navistar, Inc.