

Subject:

Service Part Update - MY13-14 Avalon Seat Back Cover - Metal Clips for E0B Campaign

Market:

USA

Service Category:

Vehicle Interior

Section:

Seat

Applicability:

MY13-14 Avalon / Avalon HV

APPLICABLE VEHICLES

2013-2014

Avalon

2013-2014

Avalon HV

CONDITION

During the E0B campaign for MY13-14 Avalon seat heaters, some of the metal clips attaching the seat back cover to the seat frame may become bent / damaged and no longer allow the seat back cover to fit properly on the frame.

Previously, the entire seat back cover assembly (P/N: 71705-07071-A0/B0/C0) had to be replaced to repair the vehicle, now the metal clips are available as a service part.

RECOMMENDATIONS

Replace damaged / bent clip(s) with new clip(s)

NOTE: If the dog house retainer on the seat back cover itself is also damaged in any way, replace the entire seat back cover assembly (P/N: 71705-07071-A0/B0/C0)

Service part information:

Part Number:
71898-07040

Part Name:
Hook, seat cover

Quantity / Vehicle
1 - 4 (pending on quantity damaged)

LINK REFERENCES

This Tech Tip does not contain any link references

