Bulletin No.: PIT5334

Date: Oct-2014

# PRELIMINARY INFORMATION

Subject: Dome Lamps Flash On And Off When Operating Brake Pedal Or Turn Signal

Models: 2015 Cadillac Escalade Models

2015 Chevrolet Suburban, Tahoe

2015 GMC Yukon Models

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

#### Condition/Concern

Some owners may comment when the dome lamps are off, if the brake pedal is applied or turn signal is operated, the dome lamp will flash on and off. This issue may also occur when other electrical loads are operated, but the brake pedal and left turn signal are the most common. There will be no DTCs related to this issue

**Note:** This concern is a different issue than described in the latest version of PI1268. The issue in PI1268 is while the dome lamps are on and the brake pedal is applied or turn signals are flashing there is a change in the dome lamp intensity.

### **Recommendation/Instructions**

To correct this concern, replace both front overhead console lamps with GM Part Number 23104411.

#### **Parts Information**

Part Number	Description	Qty
23104411	Front Courtesy Lamp	2

## **Warranty Information**

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2080338*	Replace Both Front Overhead Courtesy Lamps	.4 Hrs
* This is an unique labor operation for bulletin use only. This will not be published in the Labor Time Guide.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

