

9002158 02/13/2014 MY08-09 JC, RT

GPOP - Issue Review System

Part Number: 05026875A\$

Part Description: Wireless Ignition Node Receiver.

Issue Wireless Ignition Node Receiver part number 05026875AE is no longer available.

Description: The following kits are available as replacements.~
68241059AA kit for Journey (JC) and Dodge (RT) 3 button FOB.~
68241066AA kit for Chrysler (RT) 6 button FOB.~
68241069AA kit for Dodge (RT) 6 button FOB.~
68241070AA kit for Chrysler (RT) 3 button FOB.~
68241076AA kit for Dodge (RT) 5 button FOB.~

~____~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
