

9002228 02/12/2014 MY10-12 DJ, DS, D2, DX

GPOP - Issue Review System

Part Number: 55277406A\$, 55277407A\$, 55277408A\$, 68037409A\$

Part Description: Rear Window Glass Assembly

Issue ISSUE 1: [P/N 55277406AA]~

Description: It is not necessary to replace the entire rear power window glass assembly when the rubber channel on top of sliding glass is falling out. Order only the replacement rubber channel (P/N 68080080AA) or the plastic slider (P/N 68166526AA) depending on which part is damaged.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.