



Service Bulletin

File in Section: -

Bulletin No.: P11295


Date: August, 2014

PRELIMINARY INFORMATION

Subject: Accessory Splash Guards Missing Nuts and Bolts

Models: 2015 Chevrolet Colorado
2015 GMC Canyon
Equipped with Accessory Splash Guards (RPO VQK)

Condition/Concern



Some technicians may notice the fasteners that go into the body of the wheel well are missing when installing the accessory splash guards. ³⁹⁶⁷⁵³⁷

This may be due to the vehicle being built without a wheelhouse liner.

Recommendation/Instructions

Order the nuts and screws missing on the vehicle needed for the accessory splash guards listed below.

Parts Information

Part Number	Description	Qty
11570637	BOLT/SCREW-TRUSS HD W/SPL SHLDR	2
11609952	NUT-PUSH IN	2

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
0580118*	Nuts and Screws Installation for Accessory Splash Guards	0.0 hr

*This is a unique labor operation for bulletin use to cover part cost only. The required labor is included in 0512172 for the LPO accessory and included in the customer paid installation cost when installed as an ACO.