



Service Bulletin

File in Section: -

Bulletin No.: PI02003C

Date: August, 2014

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Missing Alignment Dowel Pin

Models: 2002-2015 Cadillac Escalade Models
2000-2015 Chevrolet Avalanche, Suburban, Tahoe
2008-2012 Chevrolet Colorado
1999-2015 Chevrolet Silverado
2008-2012 GMC Canyon
2000-2015 GMC Yukon Models
1999-2015 GMC Sierra
2003-2009 Hummer H2

This PI was superseded to update Model Years. Please discard PI02003B.

Condition/Concern

While performing a front end alignment it may be noticed that the upper control arm bracket alignment pin is missing. This pin serves as a pilot for the alignment cam when adjusting the front caster and camber

Recommendation/Instructions

If the pin is missing, a 1/4 inch dowel rod or a punch can be utilized as a temporary alignment aid to properly center the cam to the bracket, while making adjustments and torqueing the control arm nuts.