



SI B65 30 09  
Audio, Navigation, Monitors, Alarms, SRS

January 2014  
Technical Service

---

This Service Information bulletin supersedes SI B65 30 09 **dated April 2010.**

**NEW** designates changes to this revision

**SUBJECT**

**Enabling Code FSC/SWT - Enabling the Navigation System Map at QC1**

**MODEL**

**NEW** .

E71

E84

E89

F01

F02

F02H

F06

F07

F10

F10H

F12

F13

F15

F22

F25

F30

F30H

F31

F32

F33

F34

With option 609 (Navigation System Professional)

#### SITUATION

The navigation system is inoperative unless the map is enabled during the QC1 Pre-Delivery Check.

#### INFORMATION

New vehicles come equipped with a navigation road map that must be enabled via an enable code (FSC). This process is part of the QC1 Pre-Delivery Check performed with the ISID (ISTA Diagnosis).

**IMPORTANT:** There is no programming involved!

#### PROCEDURE

Enabling the navigation map at QC1 requires the use of an “**INITIAL**” enabling code.

**Note: In order to avoid unnecessary delays in the QC1 process, order this “INITIAL” enabling code at least 24 hours before performing QC1. This code is valid for 30 days, after which it is automatically deleted.**

Unlike other enabling codes, these “**INITIAL**” codes are available free of charge from the Parts department (nominal charge \$.01). The part number for the “**INITIAL**” enabling code is published in the EPC. It must be ordered as a coded part via the parts ordering process.

The delivery of the enabling code takes place in the After Sales Assistance Portal (ASAP).

**Note:** If a BMW center has two dealer numbers, when retrieving the enabling code, be sure to use the same dealer number that your Parts department used when the original order was placed.

#### **Procedure for ordering and downloading the initial enabling code:**

**Refer to attachment A.**

#### **Procedure for activation of the navigation system map using ISTA:**

**Refer to attachment B.**

For a general overview on the enabling code ordering and downloading process, refer to [SI B09 04 09](#).

#### **NEW PARTS INFORMATION**

Part Number	Description	Quantity
Refer to EPC, VIN- specific	Enable code, initial, Professional GPS	1

**WARRANTY INFORMATION**

Since this process is part of the new QC1 Pre-Delivery Check, no additional warranty costs can be claimed.

**ATTACHMENTS**

View PDF attachment [B653009 Attachment A.](#)

View PDF attachment [B653009 Attachment B.](#)

[ Copyright ©2014 BMW of North America, Inc. ]