

Measure no.

US 57540635-01

Subject

Deleting running-in rpm limit

Status date (mm/dd/yy)

3/17/14

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

3/17/14

Created by

Thomas Eichholz

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K47

Engine

4-ZYL

Body**Production period (from/to)**

(mm/dd/yy)

Comment on production period

/

Feedback (all cases relating to

measure up to) (mm/dd/yy)

Complaint

The "Deactivate nMOT max (engine-speed limiter)" action is not an option in the "Vehicle tasks" submenu for S1000R (K47).

Cause

Errors in the "Running-in Check Maintenance Schedule" check sheet.
Model S 1000 R (K47) comes from the factory without running-in rpm limit.

Measure

The "Deleting running-in rpm limit" item that is part of the 00 00 119 BMW running-in check can be disregarded for the S 1000 R (K47).
Mark the maintenance check sheet with "Not applicable" (N/A).

Complaint

Fault location	Fault type	Fault place	Fault conditions
13/61 DME engine control unit	Component: Electrical system, electronics faulty		Engine on

Cause

#	Fault location	Fault type	Fault place
---	----------------	------------	-------------

1	13/61 DME engine control unit	Component: Electrical system, electronics faulty
	Repair Task	Special Clearance Area
	No action	No Powertrain

Progman / DIS / ISTA / ISTA/P