

Vehicle rocks or lurches after sitting in park for several minutes

Topic number	LI27.60-P-059304
Version	1
Design group	27.60 Gearshift, control
Date	07-01-2014
Validity	Model 117 with 7G-DCT
Reason for change	
Reason for block	

Complaint:

Vehicle rocks or lurches once after sitting in park with engine running for roughly 10 minutes

Cause:

When placing the 7G-DCT in park, along with the park pawl engaging, the brakes will be held to increase comfort before applying parking brake.

The service brakes are released and the vehicle allowed to catch on the park pawl when:

- The engine is shut off
- Roughly 10 minutes has passed
- Parking brake is applied

Remedy:

Vehicle is functioning as designed, do not replace parts.

Please advise the customer of the function of this system and suggest to always use parking brake.

Symptoms
Power transmission / Automatic transmission / Automatic transmission operation / Drive position selection / Function / General
Power transmission / Automatic transmission / Automatic transmission - function / Engaging process

Validity		
Vehicle	Engine	Transmission
CLA (117)	*	724