



Technical product information

Topic	HVAC Potential spurious Diagnostic Trouble Code (DTC)
Market area	Worldwide Bentley (1WBE)
Brand	Bentley
Transaction No.	2036267/1
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
08 - Air Conditioning	01592: Air quality sensor -G238	14: Faulty	Intermittent

New customer code

Object of complaint	Complaint type	Position
Air-conditioning -> Ventilation, air distribution -> Recirculation control -> Automatic recirculation with air quality sensor	functionality -> without function / defect	

New workshop code

Object of complaint	Complaint type	Position
Air-conditioning -> Operation, climate control -> Air quality sensor	functionality -> without function / defect	

Vehicle data

Continental series

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
39*	2004	E		*	*	*
39*	2005	E		*	*	*
39*	2006	E		*	*	*
39*	2007	E		*	*	*
39*	2008	E		*	*	*
39*	2009	E		*	*	*
39*	2010	E		*	*	*
39*	2011	E		*	*	*
39*	2012	E		*	*	*
39*	2013	E		*	*	*
39*	2014	E		*	*	*
39*	2015	E		*	*	*

39*	2016	E		*	*	*
39*	2017	E		*	*	*
39*	2018	E		*	*	*
3W*	2004	E		*	*	*
3W*	2005	E		*	*	*
3W*	2006	E		*	*	*
3W*	2007	E		*	*	*
3W*	2008	E		*	*	*
3W*	2009	E		*	*	*
3W*	2010	E		*	*	*
3W*	2011	E		*	*	*
3W*	2012	E		*	*	*
3W*	2013	E		*	*	*
3W*	2014	E		*	*	*
3W*	2015	E		*	*	*
3W*	2016	E		*	*	*
3W*	2017	E		*	*	*
3W*	2018	E		*	*	*
4W*	2014	E		*	*	*
4W*	2015	E		*	*	*
4W*	2016	E		*	*	*
4W*	2017	E		*	*	*
4W*	2018	E		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SCB	***	**	*	*	*	000001	999999		

Documents

Document name
master.xml
master.doc

 Connection offline

Technical product information

Transaction No.: **2036267/1**

HVAC Potential spurious Diagnostic Trouble Code (DTC)

Customer statement / workshop findings

Customer will not be aware of this code / Workshop may discover this code whilst running a Diagnostic Trouble Code log as part of other investigations on the car

Technical background

At low ambient temperatures a spurious fault code may be logged by the HVAC control module in reference to the air quality sensor. The code is stored without being accompanied by any functional failure in the system

Production change

.

Measure

The following may be seen during routine interrogation of vehicle systems do not take any investigative action in response to the following fault code unless there is an actual fault evident in the system or a fault in the system has been reported by the owner.

Address 08 – Air conditioner/heater electronics

01592 014

Air quality sensor – G238

Faulty

Status: Intermittent