

SERVICE CAMPAIGN BULLETIN


CAMPAIGN REF: 02B
TITLE : HVAC Drain tube valve replacement
DOCUMENT # : 12 A 004
AFFECTED VEHICLES : McLaren P1™

SITUATION : Quality Engineering at McLaren Automotive have identified a potential risk of water leaking inside the cabin into the driver and passenger footwell areas.

PROCEDURE : Please follow the procedure outlined in this document to replace the HVAC drain tube valve.


REMOVAL:

1. Lift the vehicle on platform. Please refer to BA-RM-01A001-00-001 – Secure/Lift vehicle on platform.
2. Locate the HVAC drain tube valve in the front floor panel (1).



Care Point: It is not necessary to remove the drain tube to replace the valve.

3. Remove the valve (2) from the drain tube using a pair of long nose pliers.



INSTALLATION:

4. Install the new drain valve 11A7034CP into the drain tube, ensuring that it is correctly located (3).



Please contact your Regional Aftersales Manager should you have any questions relating to the information contained in this bulletin.

WARRANTY INFORMATION

DESCRIPTION	RESOLUTION CODE	TOTAL REPAIR TIME
HVAC drain tube valve replacement	BCAS0102A12C1T01	0.1 hours

PARTS INFORMATION

PART DESCRIPTION	PART NUMBER	QUANTITY	ORDER PROCESS
HVAC Drain Tube Valve	11A7034CP	1	Unipart *

* McLaren will auto issue the parts to each dealer based on your vehicle parc. If additional parts are required they must be ordered via Unipart.
