Technical Bulletin



SERVICE BULLETIN

 Classification:
 Reference:
 Date:

 RS14-001
 NTB14-004
 February 3, 2014

2014 ALTIMA; PARTS ORDER FORM FOR AIR BAG DIAGNOSIS SENSOR UNIT

APPLIED VEHICLES: 2014 Altima (L33)

SERVICE INFORMATION

When replacing the Air Bag Diagnosis Sensor Unit in an Applied Vehicle:

- **Do Not** order the part listed in WINFAST. The part number shown in WINFAST is incorrect.
- The correct part number is listed below. You must use the Parts Order Form on page 2 to order this part.

DESCRIPTION	CORRECT PART #	ORDER METHOD
Air Bag Diagnosis Sensor Unit (Sensor-Side Airbag Center)	98820-9HN9A	Use Parts Order Form on page 2 of this bulletin

NOTE: If the incorrect part is ordered and installed on an Applied Vehicle, a U1000 DTC or problem with the remote start feature may occur.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS ORDER FORM

FOR NTB14-004 2014 ALTIMA AIR BAG DIAGNOSIS SENSOR UNIT

INCOMPLETE ORDER FORMS WILL NOT BE PROCESSED

Dealer Code:		Order Date:			
Dealership Email Address:					
VIN Num	ber:				
PDC:	Sacramento PDC Los Angeles PDC Dallas PDC Baltimore PDC New York PDC	 Orlando PDC Chicago PDC Greenville PDC Memphis – Olive Branch PDC 			

PART NUMBER	DESCRIPTION	QUANTITY
98820-9HN9A	Air Bag Diagnosis Sensor Unit (Sensor-Side Airbag Center)	

Email the completed form to:

campaign.parts@nissan-usa.com

NOTE: This bulletin is <u>not</u> a campaign. For convenience, the above email address is being used to fulfill and expedite this part request.

2/2 NTB14-004