

<b>Reference</b>	SSM71840
<b>Models</b>	Range Rover / L322 Range Rover Sport / L320
<b>Title</b>	Brake Noise (front) 2010-12 Range Rover S/C, 2010-13 RR Sport S/C
<b>Category</b>	Chassis
<b>Last modified</b>	11-Jul-2014 00:00:00
<b>Symptom</b>	301000 Service Brake System
<b>Content</b>	<p><u>Issue:</u> Brake noise from front axle (with Brembo brakes only)</p> <p><u>Cause:</u> Under investigation</p> <p><u>Action:</u> If a customer complains of brake noise whereby the cause is not due to worn out (or nearly worn) brake pads, then please submit a TA following the guidelines set forth in SSM # 58457. At that point the TA will be reviewed and if appropriate authorization for bulletin LTB00592 to be performed will be granted. The Technical Helpline will then follow-up on the case several weeks later for any feedback received and the TA will be closed.</p> <p>LTB00592 is an L405/L494 bulletin featuring revised brake pads and to date limited trials of this brake pad on L322/L320 models have shown promising results.</p>