



# Update Prior to Sale UPS4114: Potential Transmission Filter Detachment from Oil Pan - Update

## SERVICE BULLETIN

14-JUL-14 | No.: 6-233NAS | Section: GENERAL INFORMATION | Market: CAN / USA

THIS BULLETIN UPDATES 6-231NAS

### DESCRIPTION

An issue has been identified on a number of 2015 model year F-TYPE (X152) and 2014 model year XF (X250) and XJ (X351) vehicles within the listed VIN ranges where the transmission filter may become detached from the transmission oil pan base.

### AFFECTED VEHICLES

The VIN ranges of affected vehicles are:

- F-TYPE (X152).....K11775-K12045
- XF (X250) .....U29660-U31713
- XJ (X351) .....V69257-V69749

See the attached list for specific VINs.

### WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles within your control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action.

Refer to Technical Bulletin UPS4114-2bNAS: *Potential Transmission Filter Detachment from Fluid Pan*, for detailed repair instructions.

### PARTS

\* **NOTE:** an allowance equivalent to £150.00 (approximately US\$244.50) has been provided to cover the cost of the transmission oil.

\*\* **NOTE:** when ordering parts, order only the expected percentage demand of parts identified

DESCRIPTION	PART No. / SUNDRY CODE	QTY. / VALUE	EXPECTED % OF VEHICLES REQUIRING PARTS
Transmission oil pan kit	JDE36541	1	100
Transmission oil	ZZZ999	£150.00	100

### TOOLS

Refer to Workshop Manual for any required tools

### WARRANTY

**NOTE:** Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**K238**' along with the relevant Option Code. SRO and parts information is included for information only. The drive in / drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **09 January 2015** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS / SUNDRY CODE	QTY. / VALUE*
<b>K238</b>	<b>B</b>	Install the new transmission fluid pan kit - <b>F-TYPE (X152)</b>	44.24.04	1.90	JDE36541 ZZZ999	1 £150.00
<b>K238</b>	<b>C</b>	Install the new transmission fluid pan kit - <b>F-TYPE (X152)</b>	44.24.04	1.90	JDE36541 ZZZ999	1 £150.00
		Drive in/drive out	10.10.10	0.1	-	-
<b>K238</b>	<b>B</b>	Install the new transmission fluid pan kit - <b>XF (X250) 3.0L V6 RWD</b>	44.24.04	1.20	JDE36541 ZZZ999	1 £150.00
<b>K238</b>	<b>C</b>	Install the new transmission fluid pan kit - <b>XF (X250) 3.0L V6 RWD</b>	44.24.04	1.20	JDE36541 ZZZ999	1 £150.00
		Drive in/drive out	10.10.10	0.10	-	-
<b>K238</b>	<b>B</b>	Install the new transmission fluid pan kit - <b>XF (X250) 3.0L V6 AWD</b>	44.24.04	1.40	JDE36541 ZZZ999	1 £150.00
<b>K238</b>	<b>C</b>	Install the new transmission fluid pan kit - <b>XF (X250) 3.0L V6 AWD</b>	44.24.04	1.40	JDE36541 ZZZ999	1 £150.00
		Drive in/drive out	10.10.10	0.10	-	-
<b>K238</b>	<b>B</b>	Install the new transmission fluid pan kit - <b>XF (X250) 5.0L V8</b>	44.24.04	1.60	JDE36541 ZZZ999	1 £150.00
<b>K238</b>	<b>C</b>	Install the new transmission fluid pan kit - <b>XF (X250) 5.0L V8</b>	44.24.04 10.10.10	1.60 0.10	JDE36541 ZZZ999	1 £150.00
		Drive in/drive out			-	-
<b>K238</b>	<b>B</b>	Install the new transmission fluid pan kit - <b>XJ (X351) 3.0L V6 AWD</b>	44.24.04	1.60	JDE36541 ZZZ999	1 £150.00
<b>K238</b>	<b>C</b>	Install the new transmission fluid pan kit - <b>XJ (X351) 3.0L V6 AWD</b>	44.24.04	1.60	JDE36541 ZZZ999	1 £150.00
		Drive in/drive out	10.10.10	0.10	-	-

\* **NOTE:** an allowance equivalent to £150.00 (approximately US\$244.50) has been provided to cover the cost of the transmission oil.

*Normal Warranty policies and procedures apply*

UPS4114: Affected VIN List

CANADA

VIN	Retailer Number / Name	Sold / Retailer Stock?
K11779	4498 Jaguar Thornhill	Retailer Stock
U30371	4498 Jaguar Thornhill	Retailer Stock

USA

F-TYPE [X152]		Sold / Retailer Stock?
K11926	5445 Jaguar Hartford	Retailer Stock
K11978	5670 White Plains Jaguar	Retailer Stock
K11979	5311 Jaguar Monmouth	Sold
K11982	5703 Galpin Jaguar	Sold
K11983	5605 Jaguar West Chester	Sold
K11998	5726 Paretti Jaguar of Baton Rouge	Retailer Stock
K12000	5536 Jaguar Naples	Sold
K12038	5756 Imperial Motors Jaguar of Lake Bluff	Retailer Stock
XF [X250]		Sold / Retailer Stock?
U29660	0696 Alpine Jaguar	Retailer Stock
U29678	5628 Jaguar Newport Beach	Retailer Stock
U31229	5395 Jaguar West Ashley	Sold
U31237	5305 Jaguar St. Louis	Sold
U31245	5743 Jaguar Merriam	Sold
U31268	5322 Jaguar Birmingham	Retailer Stock
U31294	5504 Brown's Jaguar	Sold
U31310	5774 Jaguar Westside	Sold
U31326	5756 Imperial Motors Jaguar of Lake Bluff	Retailer Stock
U31334	5427 Madison Jaguar	Sold
U31342	5796 Jaguar Des Moines	Sold
U31350	5302 Jaguar Paramus	Retailer Stock
U31358	5618 Hennessy Jaguar	Retailer Stock
U31361	5793 Jaguar Charleston	Retailer Stock
U31374	5302 Jaguar Paramus	Retailer Stock
U31382	5302 Jaguar Paramus	Sold
U31390	5396 Jaguar Cincinnati	Retailer Stock
U31442	5725 Manhattan Jaguar/NYC	Retailer Stock
U31586	5446 Jaguar Winston Salem	Retailer Stock
U31601	5446 Jaguar Winston Salem	Sold
U31609	5759 Bobby Rahal Jaguar	Sold
U31702	5793 Jaguar Charleston	Sold
U31713	5664 Jaguar Hunt Valley	Sold
XJ [X351]		Sold / Retailer Stock?
V69631	5671 Ken Garff Jaguar	Retailer Stock
V69651	0078 Stevinson Imports, Inc.	Sold
V69683	5605 Jaguar West Chester	Sold
V69749	1459 Howard Orloff Jaguar/Volvo	Sold