

9003084 04/23/2014 MY14 VF

GPOP - Issue Review System

Part Number: 5QM90LXUA\$

Part Description: Radio

Issue Description: If this radio is installed in a vehicle equipped with the Radio Prep Package (sales code RA9), the vehicle harness connector will require relocation of the of A4, F20(BL/LG) and A7, A933 (RD/YL) circuits for radio operation. These two terminals must be swapped in the the connector. Failure to do so will result in the radio prompting the user to enter the security code every time the key is cycled.