



# Tech Tips

TT 37-14-01

Date: October 31, 2014

**2014-2015 Passat/CC, Eos, Beetle, GTI/Golf – No Mechatronic  
Communication DTC 01315**

For communication faults set in various modules indicating loss of, or no communication with the mechatronic, please inspect the barrel connector lock for proper installation. If you find that the connector was not properly secured, inspect the terminals for damage. If no damage is found, reconnect the barrel connector and clear the faults.