



Recall Bulletin



F/CMVSS NONCOMPLIANCE RECALL

SUBJECT: Passenger Airbag Partial Deployment

MODELS: 2015 Cadillac Escalade, Escalade ESV
Previously Involved in Recalls 14220 or 14249

All vehicles involved in noncompliance recalls 14220 and 14249 have been transferred to this recall. All vehicles in this recall require an inspection of the IP assembly in the vehicle. Vehicles involved in this recall were previously repaired under noncompliance recall 14220 or 14249. These vehicles may have been repaired with suspect parts. To ensure a suspect part was not installed in the vehicle, **these vehicles are to be re-inspected to ensure that a correct part was used during the repair.**

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

CONDITION

General Motors has decided that certain 2015 model year Cadillac Escalade and Escalade ESV vehicles fail to conform to Federal/Canada Motor Vehicle Safety Standard 208 for occupant crash protection. The passenger airbag module is attached to a chute adhered to the backside of the instrument panel with an infrared weld that was not sufficiently heated. This results in a partial deployment which increases risk of injury in a crash.

CORRECTION

Dealers are to inspect the instrument panel assembly and, if necessary, replace it.

VEHICLES INVOLVED

All involved vehicles are identified by Vehicle Identification Number on the Investigate Vehicle History screen in GM Global Warranty Management system. Dealership service personnel should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.

For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared and will be provided to dealers through the GM GlobalConnect Recall Reports. Dealers will not have a report available if they have no involved vehicles currently assigned.

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.

PART INFORMATION

Parts, if required, to complete this recall are to be obtained from General Motors Customer Care and Aftersales (GMCC&A). Please refer to your "involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Part Number	Description	Quantity/Vehicle
23471519	Panel, IP Upper Trim (Black) RH (RPO 4AA)	1 (if req'd)
23471520	Panel, IP Upper Trim (Cocoa) RH (RPO 4ER)	1 (if req'd)
11611805	Clip, W/S Upr G/Mldg	1 (if panel replaced)

SERVICE PROCEDURE

Note: The purpose of the inspection procedure below is to determine if the right instrument upper trim panel must be replaced. Carefully read and follow the inspection procedure.

Use the following steps to remove the required interior trim, record the number from the tag on the right hand instrument trim panel and determine if the panel needs to be replaced.

1. Remove the instrument panel extension. Refer to Instrument Panel Extension Replacement (Cadillac) in SI.



3909687

2. Locate the white paper tag on the instrument panel upper trim panel (there are two labels, it is the label toward the center of the vehicle).
3. Using a digital camera or the camera function on a cell phone, take a clear picture of the label.



3909688

4. Compare the last 9 numbers on the label to the Suspect Label Number Table below. The label will appear upside down in the photograph, rotate as required.
 - **If the number does NOT appear on the list**, no further action is required. Reinstall the instrument panel extension.
 - **If the number IS on the list**, proceed to the Replacement Procedure below.

Suspect Label Number Table

H77168489	H77168542	H77178075	H77240156	H77240214	H77271636	H77284598
H77168490	H77168543	H77178077	H77240157	H77240215	H77271637	H77284601
H77168491	H77168544	H77178078	H77240158	H77240219	H77271638	H77284602
H77168492	H77168545	H77178080	H77240159	H77240220	H77271639	H77284603
H77168494	H77168546	H77178081	H77240162	H77240221	H77271640	H77284604
H77168495	H77168547	H77178083	H77240164	H77240223	H77271641	H77284605
H77168496	H77168548	H77178084	H77240165	H77240224	H77271642	H77284606
H77168497	H77168549	H77178085	H77240166	H77240226	H77271643	H77284608
H77168498	H77168550	H77178086	H77240167	H77240227	H77271644	H77284610
H77168500	H77168551	H77178088	H77240168	H77240228	H77271645	H77284611
H77168501	H77168552	H77178089	H77240169	H77240229	H77271646	H77284612
H77168502	H77168553	H77178091	H77240170	H77240232	H77271648	H77284614
H77168503	H77168554	H77181687	H77240171	H77240233	H77271649	H77284616
H77168504	H77168555	H77181691	H77240172	H77240234	H77271650	H77284618
H77168505	H77168556	H77181692	H77240173	H77240235	H77271651	H77284619
H77168507	H77168557	H77181693	H77240174	H77240236	H77271652	H77284620
H77168509	H77168560	H77181694	H77240175	H77240237	H77271653	H77284621
H77168510	H77168561	H77181696	H77240177	H77240286	H77271654	H77284622
H77168511	H77168562	H77207746	H77240178	H77240287	H77271655	H77284624
H77168512	H77168563	H77207747	H77240179	H77240288	H77271656	H77284625
H77168513	H77168564	H77207749	H77240182	H77240289	H77271657	H77284626
H77168514	H77168565	H77207750	H77240183	H77240290	H77271658	H77284628
H77168515	H77168566	H77207751	H77240184	H77240291	H77271659	H77284630
H77168516	H77168567	H77207752	H77240185	H77240292	H77271660	H77284631
H77168517	H77168569	H77207753	H77240186	H77240293	H77271661	H77284632
H77168518	H77168571	H77207754	H77240187	H77240294	H77271662	H77284634
H77168519	H77168573	H77207755	H77240188	H77240295	H77271663	H77284635
H77168520	H77168574	H77207756	H77240189	H77240297	H77271664	H77284636
H77168521	H77168576	H77207757	H77240190	H77240298	H77271665	H77284639
H77168522	H77168577	H77207759	H77240191	H77240299	H77271667	H77284644
H77168523	H77168578	H77207763	H77240192	H77240300	H77271668	H77284646
H77168524	H77168579	H77207764	H77240196	H77240301	H77271669	H77284647
H77168525	H77168581	H77207766	H77240197	H77240302	H77271670	H77284648
H77168526	H77168583	H77207769	H77240198	H77240303	H77271671	H77284650
H77168527	H77168584	H77207770	H77240199	H77240304	H77271672	H77284651
H77168528	H77168585	H77240145	H77240200	H77240305	H77271673	H77284653
H77168529	H77168587	H77240146	H77240202	H77240306	H77271674	H77284655
H77168530	H77168591	H77240147	H77240203	H77240307	H77271675	H77284656
H77168531	H77168633	H77240148	H77240204	H77240308	H77271676	H77284657
H77168532	H77168634	H77240149	H77240205	H77240310	H77271677	H77284658
H77168533	H77168635	H77240150	H77240206	H77240311	H77271678	H77284659
H77168536	H77168636	H77240151	H77240207	H77240312	H77271679	H77284660
H77168537	H77168637	H77240152	H77240208	H77240314	H77271680	H77284661
H77168539	H77168638	H77240153	H77240211	H77240315	H77271681	H77284662
H77168540	H77178036	H77240154	H77240212	H77240317	H77271683	H77284664
H77168541	H77178074	H77240155	H77240213	H77271635	H77284597	H77284665

H77284667	H77304798	H77304855	H77311371	H77311424	H77317242	H77322611
H77284668	H77304799	H77304856	H77311372	H77311425	H77317243	H77322612
H77284669	H77304800	H77304858	H77311373	H77311426	H77317246	H77322613
H77284671	H77304802	H77304859	H77311374	H77311427	H77317247	H77322614
H77284672	H77304803	H77304860	H77311375	H77311428	H77317248	H77322615
H77284673	H77304804	H77304861	H77311376	H77317190	H77322563	H77322616
H77284674	H77304805	H77304862	H77311377	H77317192	H77322564	H77322617
H77284675	H77304806	H77304863	H77311378	H77317194	H77322566	H77322618
H77284676	H77304807	H77304864	H77311379	H77317195	H77322567	H77322619
H77304747	H77304808	H77304865	H77311380	H77317196	H77322568	H77322620
H77304748	H77304809	H77304866	H77311381	H77317198	H77322570	H77322621
H77304749	H77304810	H77304868	H77311382	H77317199	H77322571	H77322622
H77304753	H77304811	H77304869	H77311383	H77317200	H77322572	H77322623
H77304756	H77304812	H77304870	H77311384	H77317201	H77322573	H77322624
H77304757	H77304815	H77304873	H77311386	H77317203	H77322574	H77322625
H77304758	H77304816	H77304874	H77311387	H77317204	H77322575	H77322626
H77304759	H77304818	H77304876	H77311388	H77317205	H77322576	H77322627
H77304761	H77304819	H77304877	H77311390	H77317206	H77322577	H77322628
H77304763	H77304820	H77304878	H77311391	H77317207	H77322578	H77322630
H77304765	H77304822	H77304879	H77311392	H77317208	H77322579	H77322631
H77304766	H77304824	H77304881	H77311393	H77317209	H77322580	H77322632
H77304767	H77304826	H77304883	H77311394	H77317210	H77322581	H77322633
H77304768	H77304827	H77304884	H77311396	H77317211	H77322582	H77322634
H77304769	H77304828	H77304886	H77311397	H77317212	H77322583	H77322635
H77304770	H77304829	H77304890	H77311398	H77317213	H77322584	H77322636
H77304771	H77304830	H77304891	H77311399	H77317214	H77322586	H77322637
H77304772	H77304831	H77304892	H77311400	H77317215	H77322587	H77322639
H77304773	H77304832	H77304893	H77311401	H77317216	H77322589	H77322641
H77304774	H77304833	H77304894	H77311402	H77317217	H77322590	H77322642
H77304775	H77304834	H77304895	H77311403	H77317218	H77322591	H77323095
H77304776	H77304835	H77304896	H77311404	H77317219	H77322593	H77323336
H77304777	H77304836	H77311350	H77311405	H77317220	H77322594	H77323337
H77304778	H77304837	H77311351	H77311406	H77317221	H77322595	H77323338
H77304779	H77304839	H77311352	H77311407	H77317222	H77322596	H77323340
H77304780	H77304840	H77311353	H77311408	H77317223	H77322597	H77323342
H77304781	H77304841	H77311354	H77311409	H77317224	H77322599	H77323346
H77304782	H77304842	H77311357	H77311410	H77317225	H77322600	H77323347
H77304783	H77304843	H77311358	H77311411	H77317226	H77322601	H77323348
H77304784	H77304845	H77311359	H77311413	H77317227	H77322602	H77323349
H77304785	H77304846	H77311361	H77311414	H77317228	H77322603	H77323350
H77304786	H77304847	H77311362	H77311416	H77317229	H77322604	H77323351
H77304787	H77304848	H77311363	H77311417	H77317231	H77322605	H77323352
H77304788	H77304850	H77311365	H77311418	H77317232	H77322606	H77323353
H77304789	H77304851	H77311366	H77311419	H77317237	H77322607	H77323354
H77304791	H77304852	H77311367	H77311420	H77317238	H77322608	H77323356
H77304792	H77304853	H77311368	H77311421	H77317240	H77322609	H77323357
H77304794	H77304854	H77311370	H77311422	H77317241	H77322610	H77323358

H77323359	H77335081	H77379625	H77379678	H77413066	H77413118	H77451715
H77323360	H77335082	H77379626	H77379679	H77413067	H77413120	H77451716
H77323361	H77335083	H77379627	H77379680	H77413068	H77413121	H77451717
H77323363	H77335086	H77379628	H77379681	H77413069	H77413122	H77451719
H77323364	H77335088	H77379629	H77379682	H77413070	H77413123	H77451720
H77323365	H77335089	H77379630	H77379683	H77413071	H77413124	H77451722
H77323367	H77335113	H77379631	H77379684	H77413072	H77413125	H77451723
H77323368	H77335114	H77379635	H77379685	H77413073	H77413126	H77451725
H77323369	H77335116	H77379636	H77379687	H77413074	H77413127	H77451727
H77323370	H77335117	H77379637	H77413016	H77413075	H77413128	H77451729
H77323371	H77335118	H77379638	H77413017	H77413076	H77413129	H77451730
H77323372	H77335119	H77379639	H77413018	H77413077	H77413130	H77451731
H77323373	H77335120	H77379640	H77413021	H77413078	H77413132	H77451732
H77323374	H77335121	H77379641	H77413022	H77413080	H77413137	H77451734
H77323375	H77335122	H77379642	H77413023	H77413081	H77413138	H77451735
H77323376	H77335123	H77379643	H77413024	H77413082	H77413139	H77451736
H77323380	H77335124	H77379644	H77413025	H77413083	H77413140	H77451737
H77323381	H77335125	H77379645	H77413026	H77413084	H77413141	H77451739
H77323382	H77335126	H77379646	H77413027	H77413085	H77413144	H77451740
H77323383	H77335127	H77379647	H77413028	H77413086	H77413145	H77451741
H77323384	H77335128	H77379648	H77413029	H77413087	H77413146	H77451742
H77323385	H77335130	H77379649	H77413032	H77413088	H77413147	H77451743
H77323386	H77335131	H77379650	H77413033	H77413090	H77413148	H77451744
H77323387	H77335132	H77379651	H77413034	H77413091	H77413149	H77451746
H77323388	H77335134	H77379652	H77413035	H77413092	H77413150	H77451747
H77323389	H77335135	H77379653	H77413036	H77413093	H77413151	H77451748
H77323390	H77335136	H77379654	H77413038	H77413094	H77413152	H77451749
H77323392	H77335137	H77379656	H77413039	H77413095	H77413153	H77451750
H77323394	H77335138	H77379658	H77413042	H77413096	H77413154	H77451752
H77323729	H77335140	H77379659	H77413043	H77413098	H77413155	H77451753
H77323730	H77335153	H77379660	H77413044	H77413099	H77413156	H77451754
H77323732	H77379607	H77379661	H77413045	H77413100	H77413157	H77451755
H77323733	H77379608	H77379662	H77413046	H77413101	H77413158	H77451757
H77323734	H77379609	H77379663	H77413048	H77413102	H77413159	H77451758
H77323735	H77379610	H77379664	H77413050	H77413103	H77413160	H77451759
H77323736	H77379611	H77379665	H77413051	H77413104	H77413161	H77451760
H77323737	H77379612	H77379666	H77413052	H77413105	H77413163	H77451761
H77323738	H77379614	H77379668	H77413054	H77413106	H77413166	H77451762
H77323739	H77379615	H77379669	H77413055	H77413107	H77413167	H77451763
H77323742	H77379616	H77379670	H77413056	H77413109	H77413168	H77451764
H77323743	H77379617	H77379671	H77413057	H77413110	H77413169	H77451765
H77323744	H77379618	H77379672	H77413058	H77413112	H77413170	H77451766
H77323746	H77379619	H77379673	H77413059	H77413113	H77413173	H77451767
H77323747	H77379621	H77379674	H77413060	H77413114	H77451709	H77451768
H77323748	H77379622	H77379675	H77413062	H77413115	H77451711	H77451829
H77335078	H77379623	H77379676	H77413063	H77413116	H77451712	H77451831
H77335079	H77379624	H77379677	H77413065	H77413117	H77451713	H77451832

H77451834	H77454339	H77475321	H77488472	H77496864	H77496916	H77524385
H77451835	H77454340	H77475322	H77488473	H77496865	H77496917	H77524387
H77451836	H77454341	H77475323	H77488482	H77496867	H77496918	H77524390
H77451837	H77454342	H77475324	H77488484	H77496868	H77496919	H77524391
H77451838	H77454343	H77475325	H77488501	H77496869	H77496924	H77524392
H77451839	H77454344	H77475326	H77488509	H77496870	H77496926	H77524393
H77451841	H77454345	H77475327	H77488511	H77496871	H77496927	H77524394
H77451843	H77454346	H77475328	H77488512	H77496872	H77496928	H77524395
H77451844	H77475269	H77475330	H77488513	H77496873	H77524340	H77524396
H77451845	H77475270	H77475332	H77488514	H77496874	H77524341	H77524397
H77451846	H77475272	H77475333	H77488515	H77496875	H77524343	H77524398
H77451847	H77475273	H77475334	H77488516	H77496876	H77524344	H77524399
H77451848	H77475275	H77475335	H77488517	H77496877	H77524345	H77524400
H77451852	H77475276	H77475336	H77488518	H77496878	H77524346	H77524401
H77451853	H77475278	H77475337	H77488520	H77496879	H77524347	H77524402
H77451854	H77475279	H77475338	H77488521	H77496880	H77524348	H77524403
H77451855	H77475282	H77488419	H77488522	H77496881	H77524349	H77524404
H77451857	H77475283	H77488420	H77488523	H77496882	H77524351	H77524405
H77451858	H77475284	H77488421	H77488524	H77496883	H77524352	H77524406
H77451859	H77475285	H77488422	H77488525	H77496884	H77524354	H77524407
H77451860	H77475286	H77488425	H77488526	H77496885	H77524355	H77524408
H77451861	H77475288	H77488426	H77488527	H77496886	H77524356	H77524409
H77451862	H77475289	H77488428	H77488528	H77496887	H77524357	H77559953
H77451863	H77475291	H77488429	H77488529	H77496889	H77524358	H77559954
H77451866	H77475292	H77488430	H77488530	H77496892	H77524359	H77559956
H77451867	H77475293	H77488431	H77488531	H77496893	H77524360	H77559957
H77451868	H77475295	H77488432	H77496839	H77496894	H77524361	H77559958
H77451870	H77475296	H77488433	H77496840	H77496895	H77524362	H77559959
H77451872	H77475297	H77488434	H77496841	H77496896	H77524363	H77559960
H77451873	H77475298	H77488435	H77496842	H77496897	H77524364	H77559961
H77451874	H77475299	H77488438	H77496843	H77496898	H77524365	H77559962
H77451877	H77475300	H77488439	H77496844	H77496899	H77524366	H77559965
H77451878	H77475301	H77488440	H77496847	H77496900	H77524367	H77559966
H77451879	H77475302	H77488441	H77496848	H77496901	H77524369	H77559967
H77451880	H77475303	H77488442	H77496849	H77496902	H77524370	H77559968
H77451881	H77475304	H77488443	H77496852	H77496903	H77524371	H77559969
H77451882	H77475307	H77488444	H77496853	H77496904	H77524372	H77559970
H77451883	H77475309	H77488445	H77496854	H77496905	H77524373	H77559971
H77451885	H77475311	H77488449	H77496855	H77496906	H77524374	H77559972
H77451886	H77475312	H77488450	H77496856	H77496907	H77524376	H77559973
H77451887	H77475313	H77488451	H77496857	H77496908	H77524377	H77559974
H77451888	H77475314	H77488452	H77496858	H77496909	H77524378	H77559975
H77454328	H77475315	H77488453	H77496859	H77496910	H77524379	H77559977
H77454334	H77475317	H77488454	H77496860	H77496911	H77524380	H77559978
H77454336	H77475318	H77488466	H77496861	H77496912	H77524381	H77559979
H77454337	H77475319	H77488468	H77496862	H77496913	H77524382	H77559980
H77454338	H77475320	H77488469	H77496863	H77496915	H77524384	H77559981

H77559982	H77562170	H77562232	H77580077	H77580855	H77599168	H77601221
H77559983	H77562172	H77562233	H77580078	H77580856	H77599169	H77601222
H77559985	H77562173	H77562234	H77580079	H77580857	H77599170	H77601223
H77559986	H77562174	H77562235	H77580080	H77580858	H77599171	H77601224
H77559987	H77562175	H77562237	H77580082	H77580859	H77599172	H77601225
H77559988	H77562177	H77562240	H77580083	H77580861	H77599173	H77601226
H77559989	H77562178	H77562241	H77580084	H77580862	H77599174	H77601227
H77559990	H77562179	H77562244	H77580086	H77599126	H77599175	H77601228
H77559991	H77562180	H77562246	H77580087	H77599127	H77599176	H77601229
H77559992	H77562181	H77562248	H77580089	H77599128	H77599177	H77601230
H77559993	H77562182	H77562249	H77580090	H77599129	H77599178	H77601232
H77559994	H77562184	H77562250	H77580091	H77599130	H77599179	H77601233
H77559995	H77562185	H77562251	H77580092	H77599131	H77599180	H77601235
H77559996	H77562187	H77562252	H77580093	H77599133	H77599181	H77601236
H77559997	H77562189	H77562253	H77580094	H77599134	H77599182	H77601238
H77559998	H77562190	H77562255	H77580095	H77599135	H77599183	H77601239
H77559999	H77562191	H77562258	H77580096	H77599136	H77599184	H77601240
H77560001	H77562193	H77562259	H77580099	H77599137	H77601183	H77601241
H77560002	H77562194	H77562261	H77580100	H77599138	H77601184	H77601242
H77560003	H77562196	H77562262	H77580101	H77599139	H77601186	H77601244
H77560004	H77562197	H77562263	H77580102	H77599140	H77601188	H77601245
H77560005	H77562198	H77562264	H77580103	H77599141	H77601189	H77601246
H77560006	H77562199	H77562265	H77580104	H77599142	H77601191	H77601249
H77560007	H77562200	H77562266	H77580105	H77599143	H77601192	H77601253
H77560008	H77562201	H77562267	H77580106	H77599144	H77601193	H77601254
H77560009	H77562203	H77580051	H77580108	H77599145	H77601196	H77601256
H77560011	H77562204	H77580052	H77580110	H77599146	H77601197	H77601257
H77560012	H77562206	H77580053	H77580833	H77599147	H77601199	H77601258
H77562147	H77562207	H77580054	H77580834	H77599148	H77601200	H77601259
H77562148	H77562209	H77580055	H77580835	H77599149	H77601201	H77601261
H77562149	H77562210	H77580056	H77580836	H77599150	H77601202	H77601262
H77562150	H77562212	H77580058	H77580837	H77599151	H77601203	H77601264
H77562151	H77562213	H77580059	H77580838	H77599152	H77601204	H77601266
H77562152	H77562214	H77580060	H77580839	H77599154	H77601206	H77601267
H77562153	H77562215	H77580061	H77580840	H77599155	H77601207	H77601268
H77562154	H77562216	H77580062	H77580841	H77599156	H77601208	H77601269
H77562155	H77562217	H77580063	H77580842	H77599157	H77601209	H77601270
H77562156	H77562219	H77580064	H77580843	H77599158	H77601211	H77601271
H77562157	H77562220	H77580065	H77580844	H77599159	H77601212	H77601272
H77562158	H77562221	H77580066	H77580845	H77599160	H77601213	H77601273
H77562159	H77562222	H77580067	H77580846	H77599161	H77601214	H77601275
H77562161	H77562223	H77580068	H77580847	H77599162	H77601215	H77601276
H77562162	H77562224	H77580070	H77580849	H77599163	H77601216	H77601277
H77562163	H77562225	H77580071	H77580850	H77599164	H77601217	H77601278
H77562164	H77562226	H77580073	H77580852	H77599165	H77601218	H77601279
H77562167	H77562227	H77580074	H77580853	H77599166	H77601219	H77601280
H77562168	H77562229	H77580075	H77580854	H77599167	H77601220	H77601281

H77601282	H77638085	H77648235	H77648283	H77662531	H77662582	H77666683
H77630623	H77638086	H77648236	H77662477	H77662532	H77662583	H77666684
H77630625	H77638087	H77648237	H77662478	H77662534	H77662584	H77666685
H77630626	H77638088	H77648238	H77662479	H77662535	H77662585	H77666686
H77630627	H77638091	H77648239	H77662480	H77662537	H77662586	H77666687
H77630628	H77638092	H77648240	H77662481	H77662538	H77662587	H77666688
H77630629	H77638094	H77648241	H77662482	H77662539	H77662588	H77666689
H77630630	H77638096	H77648242	H77662487	H77662540	H77662589	H77666690
H77630631	H77638097	H77648243	H77662488	H77662541	H77662590	H77666691
H77630634	H77638098	H77648244	H77662489	H77662542	H77662591	H77666692
H77630635	H77638099	H77648245	H77662490	H77662543	H77662594	H77666693
H77630636	H77638101	H77648246	H77662491	H77662544	H77662595	H77666694
H77630637	H77638102	H77648247	H77662492	H77662545	H77662596	H77666695
H77630638	H77638103	H77648248	H77662493	H77662546	H77662597	H77666696
H77630639	H77638104	H77648249	H77662494	H77662547	H77662598	H77666698
H77630640	H77638105	H77648250	H77662495	H77662548	H77662599	H77666699
H77630641	H77638106	H77648251	H77662496	H77662549	H77662600	H77666700
H77630642	H77638108	H77648252	H77662497	H77662550	H77662601	H77666701
H77630644	H77638109	H77648253	H77662498	H77662551	H77662602	H77666702
H77630645	H77638110	H77648254	H77662499	H77662552	H77662603	H77666703
H77630646	H77638111	H77648255	H77662500	H77662553	H77662604	H77666704
H77630658	H77638113	H77648256	H77662501	H77662554	H77662605	H77666705
H77630659	H77638114	H77648257	H77662502	H77662555	H77662606	H77666706
H77630660	H77638115	H77648258	H77662503	H77662557	H77662607	H77666713
H77630661	H77638116	H77648259	H77662504	H77662558	H77662608	H77666714
H77630662	H77638123	H77648260	H77662505	H77662559	H77662609	H77666715
H77638062	H77638124	H77648261	H77662506	H77662560	H77662611	H77666716
H77638063	H77638125	H77648262	H77662507	H77662561	H77662612	H77666717
H77638064	H77638126	H77648263	H77662508	H77662562	H77662613	H77666718
H77638065	H77638127	H77648264	H77662510	H77662563	H77662614	H77666719
H77638066	H77638128	H77648265	H77662511	H77662565	H77662615	H77666722
H77638068	H77638129	H77648266	H77662513	H77662566	H77662616	H77666723
H77638069	H77638130	H77648267	H77662515	H77662567	H77662617	H77666724
H77638070	H77638131	H77648268	H77662516	H77662568	H77662618	H77666725
H77638071	H77638132	H77648269	H77662517	H77662569	H77662619	H77666726
H77638072	H77638133	H77648271	H77662518	H77662570	H77662620	H77666727
H77638073	H77638135	H77648272	H77662519	H77662571	H77662621	H77666728
H77638075	H77638138	H77648273	H77662520	H77662572	H77662622	H77666729
H77638076	H77638140	H77648274	H77662522	H77662573	H77662623	H77666730
H77638077	H77638143	H77648275	H77662523	H77662574	H77662624	H77666731
H77638078	H77638145	H77648276	H77662524	H77662575	H77662625	H77666732
H77638079	H77638147	H77648277	H77662525	H77662576	H77662626	H77666734
H77638080	H77638149	H77648278	H77662526	H77662577	H77666678	H77666735
H77638081	H77638152	H77648279	H77662527	H77662578	H77666679	H77666737
H77638082	H77638157	H77648280	H77662528	H77662579	H77666680	H77666738
H77638083	H77638159	H77648281	H77662529	H77662580	H77666681	H77666739
H77638084	H77648234	H77648282	H77662530	H77662581	H77666682	H77666740

H77666742	H77702337	H77736598	H77736653	H77768445	H77768492	H77785996
H77666743	H77702338	H77736599	H77736654	H77768446	H77768493	H77785997
H77666744	H77702339	H77736600	H77736657	H77768447	H77768494	H77785998
H77666745	H77702341	H77736601	H77736658	H77768448	H77768495	H77785999
H77666746	H77702342	H77736602	H77736659	H77768449	H77768496	H77786000
H77666747	H77702343	H77736603	H77736660	H77768450	H77768497	H77786001
H77666748	H77702344	H77736604	H77736661	H77768451	H77768498	H77786002
H77666749	H77702345	H77736605	H77736662	H77768452	H77768499	H77786003
H77666750	H77702346	H77736608	H77736663	H77768453	H77768500	H77786004
H77666751	H77702347	H77736609	H77736664	H77768454	H77768501	H77786005
H77666752	H77702348	H77736610	H77736665	H77768455	H77768502	H77786006
H77666754	H77702349	H77736611	H77736666	H77768456	H77768503	H77786007
H77666755	H77702350	H77736612	H77753194	H77768457	H77768504	H77786008
H77666756	H77702351	H77736614	H77753195	H77768458	H77768505	H77786009
H77666757	H77702353	H77736615	H77753196	H77768459	H77768507	H77786010
H77666758	H77702355	H77736616	H77753198	H77768460	H77768508	H77786011
H77666759	H77702356	H77736617	H77753199	H77768461	H77768509	H77786012
H77666760	H77702357	H77736618	H77753202	H77768462	H77768510	H77786013
H77666761	H77702358	H77736619	H77753211	H77768463	H77768511	H77786014
H77666762	H77702359	H77736620	H77753228	H77768464	H77768512	H77786015
H77666763	H77702360	H77736622	H77753229	H77768465	H77768513	H77786016
H77666764	H77702361	H77736623	H77753230	H77768466	H77768514	H77786017
H77666765	H77736569	H77736624	H77753231	H77768467	H77768515	H77786018
H77666766	H77736570	H77736625	H77753232	H77768468	H77768516	H77786019
H77666767	H77736571	H77736626	H77753233	H77768469	H77768517	H77786020
H77666768	H77736572	H77736628	H77753235	H77768470	H77768518	H77786021
H77666769	H77736573	H77736629	H77753236	H77768471	H77768519	H77786022
H77666770	H77736575	H77736630	H77753238	H77768472	H77768520	H77786023
H77666771	H77736576	H77736631	H77753239	H77768473	H77768521	H77786024
H77666772	H77736579	H77736632	H77753240	H77768474	H77768522	H77786025
H77666773	H77736580	H77736633	H77753241	H77768475	H77768523	H77786026
H77666774	H77736581	H77736634	H77753242	H77768476	H77768524	H77786027
H77666775	H77736582	H77736635	H77753243	H77768477	H77768525	H77786028
H77666776	H77736584	H77736636	H77753244	H77768478	H77768526	H77786029
H77702323	H77736585	H77736637	H77753245	H77768479	H77768535	H77786030
H77702324	H77736586	H77736638	H77753246	H77768480	H77785983	H77786031
H77702326	H77736587	H77736639	H77753248	H77768481	H77785984	H77786032
H77702327	H77736588	H77736640	H77753249	H77768482	H77785985	H77786033
H77702328	H77736589	H77736642	H77768433	H77768483	H77785986	H77786034
H77702329	H77736590	H77736644	H77768436	H77768484	H77785987	H77786035
H77702330	H77736591	H77736645	H77768437	H77768485	H77785988	H77786037
H77702331	H77736592	H77736646	H77768438	H77768486	H77785990	H77786039
H77702332	H77736593	H77736647	H77768439	H77768487	H77785991	H77786040
H77702333	H77736594	H77736648	H77768440	H77768488	H77785992	H77786041
H77702334	H77736595	H77736649	H77768441	H77768489	H77785993	H77799956
H77702335	H77736596	H77736650	H77768442	H77768490	H77785994	H77799957
H77702336	H77736597	H77736652	H77768444	H77768491	H77785995	H77799959

H77799960	H77800007	H77811110	H77811161	H77811220	H77811274	H77863602
H77799961	H77800008	H77811111	H77811162	H77811221	H77811275	H77863603
H77799962	H77800009	H77811112	H77811163	H77811222	H77811276	H77863604
H77799963	H77800011	H77811113	H77811164	H77811223	H77811277	H77863605
H77799964	H77800012	H77811114	H77811165	H77811224	H77811279	H77863606
H77799965	H77800013	H77811115	H77811166	H77811225	H77811304	H77863607
H77799966	H77800014	H77811117	H77811167	H77811226	H77811305	H77863608
H77799967	H77800015	H77811118	H77811168	H77811228	H77811309	H77863609
H77799968	H77800016	H77811119	H77811170	H77811229	H77811310	H77863610
H77799969	H77800017	H77811120	H77811171	H77811230	H77811311	H77863611
H77799970	H77800018	H77811121	H77811173	H77811231	H77811312	H77863612
H77799971	H77800019	H77811122	H77811174	H77811232	H77811316	H77863613
H77799972	H77800020	H77811123	H77811176	H77811233	H77811317	H77863614
H77799973	H77800021	H77811124	H77811177	H77811235	H77850844	H77863615
H77799974	H77800022	H77811126	H77811181	H77811236	H77850845	H77863616
H77799975	H77800023	H77811127	H77811183	H77811237	H77850848	H77863617
H77799976	H77800025	H77811129	H77811184	H77811238	H77863569	H77863618
H77799977	H77800026	H77811130	H77811187	H77811239	H77863570	H77863619
H77799978	H77800027	H77811131	H77811189	H77811240	H77863571	H77863620
H77799979	H77800028	H77811132	H77811190	H77811241	H77863572	H77863621
H77799980	H77800029	H77811133	H77811191	H77811242	H77863573	H77863622
H77799981	H77800030	H77811134	H77811192	H77811243	H77863574	H77863623
H77799982	H77800031	H77811135	H77811193	H77811244	H77863575	H77863624
H77799983	H77800033	H77811136	H77811195	H77811245	H77863576	H77863625
H77799984	H77800034	H77811137	H77811196	H77811246	H77863577	H77893879
H77799985	H77800035	H77811138	H77811197	H77811247	H77863578	H77893880
H77799986	H77811087	H77811139	H77811199	H77811248	H77863579	H77893882
H77799987	H77811088	H77811140	H77811200	H77811249	H77863580	H77893884
H77799988	H77811089	H77811142	H77811201	H77811250	H77863581	H77893885
H77799989	H77811090	H77811143	H77811202	H77811251	H77863582	H77893886
H77799990	H77811091	H77811144	H77811203	H77811252	H77863583	H77893887
H77799991	H77811093	H77811145	H77811204	H77811253	H77863584	H77893888
H77799992	H77811095	H77811146	H77811205	H77811254	H77863587	H77893889
H77799993	H77811096	H77811147	H77811206	H77811256	H77863588	H77893890
H77799994	H77811097	H77811148	H77811207	H77811258	H77863589	H77893891
H77799995	H77811098	H77811149	H77811208	H77811259	H77863590	H77893892
H77799996	H77811099	H77811150	H77811209	H77811262	H77863591	H77893893
H77799997	H77811100	H77811151	H77811210	H77811263	H77863592	H77893894
H77799998	H77811101	H77811152	H77811211	H77811264	H77863593	H77893895
H77799999	H77811102	H77811153	H77811212	H77811265	H77863594	H77893896
H77800000	H77811103	H77811154	H77811213	H77811266	H77863595	H77893897
H77800001	H77811104	H77811155	H77811214	H77811268	H77863596	H77893898
H77800002	H77811105	H77811156	H77811215	H77811269	H77863597	H77893899
H77800003	H77811106	H77811157	H77811216	H77811270	H77863598	H77893900
H77800004	H77811107	H77811158	H77811217	H77811271	H77863599	H77893901
H77800005	H77811108	H77811159	H77811218	H77811272	H77863600	H77893902
H77800006	H77811109	H77811160	H77811219	H77811273	H77863601	H77893903

H77893904	H77893909	H77893914	H77893919	H77893924	H77893929	H77893934
H77893905	H77893910	H77893915	H77893920	H77893925	H77893930	H77893936
H77893906	H77893911	H77893916	H77893921	H77893926	H77893931	H77893937
H77893907	H77893912	H77893917	H77893922	H77893927	H77893932	H77893938
H77893908	H77893913	H77893918	H77893923	H77893928	H77893933	

Right Side Instrument Panel Upper Trim Panel Replacement Procedure

Note: Prior to installing the new IP assembly into the vehicle, inspect the part to ensure it is not on the suspect part list above.

1. Locate the white paper tag on the instrument panel upper trim panel (there are two labels, it is the label toward the center of the vehicle).



2. Compare the last 9 numbers on the label to the Suspect Label Number Table above.
 - If the number does NOT appear on the list, it is a good part. Proceed to Step 3.
 - If the number IS on the list, it is a suspect part. DO NOT INSTALL THE PART ON THE VEHICLE. Obtain another IP assembly and perform the part number inspection again. Once it is determined that you have a good part, proceed to Step 3.
3. Replace the right instrument panel upper trim panel. Refer to *Instrument Panel Upper Trim Panel Replacement - Right Side (Cadillac)* in SI.

Tips for removal:

- When removing the left pillar trim, use care to not break the top clip mount on the trim.
- When removing the wood trim moldings, do not pry on the corners, the wood will chip.
- When removing the left and right console side trim, open the compartment lid and detach the trim from back to front.
- When removing the center trim plate, open the trim plate door to aid in removal.



3909693

- When removing the fasteners in the center of the upper left pad, there are three screws above the center screen. Ensure these are removed, if not, forcing the trim will break the mounts.
- Place the upper trim panel on a soft surface when removing and reinstalling the air bag module to prevent damage.

Tips for installation:

- When installing the air bag module on the new panel, ensure all of the tabs are fully engaged. This can be verified by an audible “click”. Gently pull on the installed assembly to verify full engagement.



3909688

- Apply hand pressure to the top of the trim panel when installing the fasteners in the center area.
- Ensure the air bag harness is connected when installing the right upper trim panel.

Ensure the correct flat head Torx fasteners are used when reinstalling the glove box. Incorrect fasteners will prevent the glove box door from closing properly.

COURTESY TRANSPORTATION

The General Motors Courtesy Transportation program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranties. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product program is very important in maintaining

customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for Courtesy Transportation guidelines.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Labor Code	Description	Labor Time
9100638	Inspect Right IP Assembly – No Further Action Req'd	0.6
9100639	Inspect & Replace Right IP Upper Trim Panel	1.5

CUSTOMER NOTIFICATION

General Motors will notify customers of this recall on their vehicle.

DEALER RECALL RESPONSIBILITY – For US (US States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

This bulletin is notice to you that the new motor vehicles included in this recall may not comply with the standard identified above. Under Title 49, Section 30112 of the United States Code, it is illegal for a dealer to sell a new motor vehicle which the dealer knows does not comply with an applicable Federal Motor Vehicle Safety Standard. As a consequence, if you sell any of these motor vehicles without first performing the recall correction, your facility may be subject to a civil penalty for each such sale.

DEALER RECALL RESPONSIBILITY - All

All unsold new vehicles in dealer's possession and subject to this recall must be held and inspected/repaired per the service procedure of this recall bulletin before customers take possession of these vehicles.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your facility for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**