



Service Bulletin

File in Section: -

Bulletin No.: PIC5929A

Date: February, 2014

PRELIMINARY INFORMATION

Subject: Tire Learning Active Message On At Startup

Models: 2013 Cadillac ATS, SRX, XTS

This PI was superseded to add repair instructions. Please discard PIC5929.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on a "Tire Learning Active" message appearing at startup.

Recommendation/Instructions

A new calibration has been released to resolve this issue. Reprogram the IPC with the latest calibration available in TIS2WEB.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time

ADDITIONAL SI KEYWORDS:

DIC learn start TPM

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.