

**SB-10055324-1308**  
**ONLINE AUTOMOTIVE SERVICE INFORMATION**  
**FOR MARCH 2014**

44460      2012-2014 Focus - Multiple Module Communication DTCs

Some 2012-2014 Focus vehicles may exhibit multiple module communication DTCs in the BCM, PCM, TCM, SASM, RCM, OCSM, PSCM, and/or ABS modules. This concern may be the result of a HS-CAN circuit located on the underside of the front passenger seat, shorting to ground. Remove the front passenger seat and inspect the OCSM harness circuits VDB04 and VDB05 for chaffing, small nicks, or cuts between connectors C3007A and C3159. Refer to wiring diagram page 14-3. If damage is found, repair and secure the harness to the underside of the seat to prevent future chaffing. Use available service labor times.