

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR FEBRUARY 2014

SB-10055626-5738

44419 2013-2014 Fusion Titanium - MKZ - Ambient Lighting Inoperative After Engine Start

Some 2013-2014 Fusion Titanium and MKZ vehicles may intermittently exhibit the ambient lights not coming on after engine start up when in the auto lamp position even though the headlamps turn on normally. Cycling the headlamp switch off and then back on, or attempting to change the ambient light color causes the ambient lighting to come on. Do not attempt to repair this concern. Engineering is aware of the concern and is working to resolve. Continue to monitor OASIS for further updates.