

TSB#: 14-010 Job Code: 9802205 Flat Rate:
 Series Code: TSB13 Inspect only .08
 TSB14 Inspect and repair .25

DATE OF PUBLICATION: MAY 2014

**NOTE: This Technical Service Bulletin will be valid within (1) year from the original date of publication.
 NO PARTS ARE REQUIRED TO BE ORDERED FROM Starcraft.**

ACTION REQUIRED:

Inspect Sofa Base top for screws. If four (4) screws are present, no repair is required.
 If screws are not present, proceed to step 2 of instructions

MODELS / UNITS:

2014 AR-ONE Travel Trailers

21FB **E28J** 5051-5054, 5064-5066, 5069-5076, 5079-5083, 5085, 5090-5092, 5105-5106, 5109-5115,
 5120, 5122, 5126-5128, 5132-5133, 5136-5145, 5149, 5155-5157, 5159-5161, 5163-5164,
 5166-5168, 5171, 5174-5176, 5180, 5184-5185, 5190, 5199, 5202, 5208-5216

2015 AR-ONE MAXX Travel Trailers


21FB **F28J** 5051, 5099, 5105-5109, 5111, 5113-5114, 5121, 5125, 5128-5130

TOOLS/MATERIAL REQ.:

Screw Gun w/ #2 square drive bit
 (4) 8X1" Quad Screws

Instructions

- 1 Remove seat cushions from the sofa bed. Inspect the sofa base top for missing screws that attach the top to the base.



- 2 Install 4 screws in the sofa base top as indicated in the photo below.
 One screw on each end, and one at the front, one at the rear of the base top.

- 3 Replace the cushions

