

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MAY 2014**

SB-10056152-3376

44529 2013-2014 F-Super Duty Equipped With 6.7L Diesel Engine - Diagnostic Trouble Code P209F

Some 2013-2014 F-Super Duty equipped with 6.7L Diesel engines may exhibit Malfunction Indicator Lamp (MIL) illuminated with Diagnostic Trouble Code (DTC) P209F stored in the Powertrain Control Module (PCM). This DTC may occur if vehicle is operating in cold ambient temperatures below 20F/-7C. If unable to determine root cause of DTC P209F after completing PCED Pin Point Test RH Diagnostic Routines, do not replace Powertrain components (DEF Reservoir Assembly, Glow Plug Control Module). Clear the DTC and return vehicle to Customer. Note: This DTC will clear after the 4th drive cycle, if the monitor completes. Submit Global Concern Reporting (GCR) VIN Information in PTS, Under contact us WEB page section, click Report a Vehicle Concern. Engineering investigating in progress. Monitor OASIS for future updates.