

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR AUGUST 2014**

SB-10056749-9157

44889 Multi Vehicle Line - Receiver Dryer Cartridge Service Part Design Change

2011- 2014 F-SuperDuty, 2009-2014 F150, 2007-2014 Expedition/ Navigator vehicles along with service parts will be transitioning to the new 2 piece receiver dryer desiccant bag replacing the 1 piece receiver dryer cartridge. These two designs are fully interchangeable and does not affect fit, form, or function. Continue to follow Workshop Manual section 412-01 for the Removal and Installation of the Receiver Dryer Cartridge or Desiccant Bag. To install the new desiccant bag after removing the cartridge, place the bag in the condenser followed by the plug and then the plastic cap. The new desiccant bag is free floating and will not attach to the plug.