



COLLINS
BUS CORPORATION

SERVICE BULLETIN

SB-10057036-2143

Dear Collins Bus Corporation Customer

Issue Date: October 24 2014

Subject: **FUEL FILL HOSE SEAT PLATE INTERFERENCE**

Models affected: Collins Buses with Seats installed over fuel tank fill hose

This Service bulletin is intended to assist Collins Bus Distributors, their customers and /or service shops in the proper techniques for repair and maintenance. Issues described in this bulletin may not apply to all Collins Bus units. Authorized technicians will be able to decide whether or not a unit with similar issues will benefit from the provided information.

Collins Bus has been determined there may be a possible condition on some Collins School Busses that a seat mounting plate may have a sharp cut edge touching the fuel fill hose and possible weakening of the hose wall may occur over time. While no damage has been reported we feel this possibility may exist and your bus should be inspected for this possible condition.



Seat mounting plate edge
rubbing on the fuel fill hose



Upon inspection of the fuel fill hose to the mid-ship fuel tank on your Collins School Bus you find the cut edge of the seat mounting plate is directly above the fuel fill hose and is making contact with the fuel fill hose we feel adding the seat mounting plate cover will keep the sharp cut edge on the seat mounting plate away from the fuel fill hose.



To install the seat mounting plate cover you will need to remove the seat bolt closest to the fuel fill hose and slide the plate cover over the seat mounting plate aligning the holes, replacing the seat bolt and tighten to 12-14 ft. lbs.