



Tech Tips

TT 45-08-02

Date: 2008

2008> Passat - Fault Code 02543 000 Present in ABS

November 7, 2014: Update to information.

Fault code 02543 000 "Brake Vacuum Sensor no Display" may be encountered in the ABS module. This may be caused by the hydraulic brake boost function (HBV) in adaptation value 61 being turned off (value = 0). All Passat Wagons (including 4motion) and 3.6L equipped sedans with front drive should have this function turned on (value = 1). Change the adaptation value and verify the fault has cleared. Additionally, it may be necessary to lock the vehicle and allow the modules to go to sleep to clear the fault.