

SB-10057734-7145

ONLINE AUTOMOTIVE SERVICE INFORMATION FOR JULY 2014

44644 2015 Lincoln MKC - Low Headlamp Aim

Some 2015 Lincoln MKC vehicles built prior to 6/11/14 may exhibit low headlamp aim. If a vehicle exhibits this condition, refer to Workshop Manual Section 417-01 for the adjustment procedure. Make sure that the headlamps are in the low beam setting when performing this procedure. Use available service labor times.